Approved CR

IAA Macon
2200 Trade Ave.
Branch No 734
Macon, GA 31217
(478) 314-0031/(478) 314-0040
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2020 FORD FUSION**
Bodystyle/Series:	**4 Door Sedan S**
Color:	**Gray**
Mileage:	**33,032 (Verified)**
Turn-in Mileage:	-
VIN:	**3FA6P0G75LR244956**
Work Order/ Stock Number:	**46482662**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G101892X**
Vehicle Grade :	**Grade 4.3**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 215 / 60 R 16	Car Tire Size - RF 215 / 60 R 16	Car Tire Size - LF 215 / 60 R 16
Car Tire Size - LR 215 / 60 R 16	LF Tires - 9/32 inch	LR Tires - 9/32 inch
RF Tires - 9/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Assurance Maxlife	Tire Model - LR - Assurance Maxlife	Tire Model - RF - Assurance Maxlife
Tire Model - RR - Assurance Maxlife		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Multiple Scratches Heavy	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY,

WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.