Approved CR

IAA Albuquerque
4400 Broadway Blvd SE
Branch No 140
Albuquerque, NM 87105
(505) 873-2081/(505) 873-3029
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2017 FORD F-350 CHASSIS**
Bodystyle/Series:	**Regular Cab XL**
Color:	**White**
Mileage:	**25,476 (Verified)**
Turn-in Mileage:	-
VIN:	**1FDRF3GT6HEE09962**
Work Order/ Stock Number:	**46445537**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G43-2918U**
Vehicle Grade :	**Grade 1.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment


Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Diesel**	Cruise Control:	**No**
Engine Size:	**6.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	**Vinyl Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 245 / 75 R 17	Car Tire Size - RR 245 / 75 R 17
Car Tire Size - RF 245 / 75 R 17	LF Tires - 13/32 inch	LR Tires - 10/32 inch
RF Tires - 13/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - BRIDGESTONE
Tire Brand - Front Right - BRIDGESTONE	Tire Brand - Rear Left - KELLY	Tire Brand - Rear Right - KELLY
Tire Model - LR - Edge HT	Tire Model - RF - Dueler LX	Tire Model - RR - Edge HT
Tire Model - LF - Dueler LX		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Rail	Previous Repair	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Cargo Box	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Cargo Box Front Wall	Multiple Scratches Light	-	5
	Corner Panel	Peeling	-	9 To 10 Inches
	Tailgate	Rust	-	> 12 Inches
	Hood	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	1 To 2 Inches
	Right Rear Wheel	Curb Rash	-	3 To 4 Inches
	Right Corner Panel	Peeling	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.