



Approved
CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 DODGE
GRAND CARAVAN**
Bodystyle/Series: **Van SE**
Color: **Black**
Mileage: **19,294 (Verified)**
Turn-in Mileage: **-**
VIN: **2C4RDGBG3JR356416**
Work Order/
Stock Number: **46423274**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G412089V**
Vehicle Grade : **Grade 3.9**
Remarks: **-**
Announcements: **• ANNOUNCEMENTS:**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 65 R 17

Car Tire Size - LR 225 / 65 R 17

Car Tire Size - RR 225 / 65 R 17

Car Tire Size - RF 225 / 65 R 17

LF Tires - 7/32 inch

LR Tires - 9/32 inch

RF Tires - 7/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - YOKOHAMA

Tire Brand - Front Right - YOKOHAMA

Tire Brand - Rear Left - YOKOHAMA

Tire Brand - Rear Right - YOKOHAMA


Tire Model - RF - Avid S33

Tire Model - RR - Avid S33

Tire Model - LR - Avid S33

Tire Model - LF - Avid S33

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Heavy Scratch	-	7 To 8 Inches
	Lift Gate	Heavy Scratch	-	1/2 To 1 Inch
	Right Sliding Door	Heavy Scratch	-	7 To 8 Inches
	Left Qtr Panel	Heavy Scratch	-	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.