



Approved CR

Dealers Auto Auction of Little Rock
4600 S University Ave
Little Rock , AR 72204
501-904-9988
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
FUSION
HYBRID
4 Door**

Bodystyle/Series: **Vehicle S 4D
SEDAN**

Color: **GRAY**

Mileage: **59,062
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **3FA6P0UU8JR254307**

Work Order/
Stock Number: **000072938**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G102413V**

Vehicle Grade : **Grade 4.1**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment


Additional Equipment:

4th Passenger Door	ABS Brakes	Air Conditioning
Automatic Headlights	Auxiliary Pwr Outlet	Bluetooth Connection
Brake Assist System	CD Player	Car Tire Size - LR tire size P225/50VR17
Car Tire Size - RR tire size P225/50VR17	Car Tire Size - RF tire size P225/50VR17	Car Tire Size - LF tire size P225/50VR17
Child Safety Locks	Cruise Control	Cylinders - 4
Daytime Running Lights	Driver Air Bag	Empty Weight - 3615 lb
Engine Immobilizer	Floor Mats	Front Wheel Drive
Front Wheel Drive	Independent Climate Control	Intermittent Wipers
Keyless Entry	Keyless Start	LF Tires - 8/32 inch
LR Tires - 8/32 inch	MP3 Radio	Master Key - 2key(s)
Motor Fuel Type - Other	Pass. Air Bag	Power Brakes
Power Lock	Power Mirrors	Power Steering
Power Trunk/Liftgate	Power Windows	Privacy Glass
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Rear Defrost
Remote Trunk Release	Reverse Camera	Seat Trim - Cloth
Security System	Side Airbags - Front	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tilt Wheel
Tire Brand - Front Left - LF tire mfg Hankook	Tire Brand - Front Left - Hood	Tire Brand - Front Right - RF tire mfg Hankook
Tire Brand - Rear Left - LR tire mfg Hankook	Tire Brand - Rear Right - RR tire mfg Hankook	Tire Pressure Monitor System
Traction Control	Transmission - Automatic Transmission w/ Overdrive	Trip Computer
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		

Non Chargeable Damages



Photo	Item	Damage	Action	Severity
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Deck Lid	Chipped	Repair	1
	Hood	Chipped	Repair	10 Or More
	Left Front Door	Multiple Scratches Light	Repair	2
	Left Rear Door	Dent(S) W/ Paint Dmg	Repair	< 1/8 Inch
	Left Rear Door	Light Scratch	Repair	3 To 4 Inches
	Roof	Previous Repair	Repair	Substd Orange Peel
	Right Front Door	Dent(S) W/No Paint Dmg	Repair	2 To 3 Inches
	Right Rear Door	Dent(S) W/No Paint Dmg	Repair	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.