Approved CR

IAA San Diego
2380 Britannia Blvd
Branch No 116
San Diego, CA 92154
(619) 710-2866/(619) 710-2878
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2021 MAZDA MAZDA3**
Bodystyle/Series:	**4 Door Sedan 2.5 S**
Color:	**Blue**
Mileage:	**23,914 (Verified)**
Turn-in Mileage:	-
VIN:	**3MZBPAAL2MM203541**
Work Order/ Stock Number:	**46379743**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G131827X**
Vehicle Grade :	**Grade 2.2**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /-**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment


Additional Equipment:

Car Tire Size - LF 205 / 60 R 16	Car Tire Size - LR 205 / 60 R 16	Car Tire Size - RR 205 / 60 R 16
Car Tire Size - RF 205 / 60 R 16	LF Tires - 7/32 inch	LR Tires - 7/32 inch
RF Tires - 5/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - CONTINENTAL
Tire Brand - Front Right - CONTINENTAL	Tire Brand - Rear Left - CONTINENTAL	Tire Brand - Rear Right - CONTINENTAL
Tire Model - RR - Procontact TX	Tire Model - RF - Procontact TX	Tire Model - LR - Procontact TX
Tire Model - LF - Procontact TX		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Collision Avoidance	On	-	Unacceptable
	Warning - Traction Control	On	-	Unacceptable
	Warning Light - Abs	On	-	Unacceptable
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning Light - Wrench	On	-	Unacceptable
	Warning Light - Engine	On	-	Unacceptable
	Warning - Tire Pressure	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Air Bag	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Left Qtr Panel	Chipped	-	10 Or More
	Rear Bumper	Multiple Scratches Heavy	-	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.