



Approved CR

Dealers Auto Auction of Little Rock
4600 S University Ave
Little Rock , AR 72204
501-904-9988
WHOLESALE ASSESSMENT ONLY

Make/Model: **2022 FORD
FURGONETA
DE
PASAJEROS
TRANSIT
3 Door**

Bodystyle/Series: **Vehicle XL
WAGON
RWD 130 WB**

Color: **WHITE**

Mileage: **84,338
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **1FMZK1Y85NKA62308**

Work Order/
Stock Number: **000072904**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G421127Y**

Vehicle Grade : **Grade 4.1**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

3rd Row Seat	ABS Brakes	Air Conditioning
Automatic Headlights	Auxiliary Pwr Outlet	Bluetooth Connection
Brake Assist System	Car Tire Size - LR tire size LT235/65SR16	Car Tire Size - RR tire size LT235/65SR16
Car Tire Size - RF tire size LT235/65SR16	Car Tire Size - LF tire size LT235/65SR16	Cruise Control
Cylinders - 6	Daytime Running Lights	Driver Air Bag
Empty Weight - 5631 lb	Engine Immobilizer	Independent Climate Control
Intermittent Wipers	Keyless Entry	LF Tires - 4/32 inch
LR Tires - 4/32 inch	Lane Departure System	Master Key - 1key(s)
Motor Fuel Type - Gas	Pass. Air Bag	Power Brakes
Power Lock	Power Mirrors	Power Steering
Power Windows	Privacy Glass	RF Tires - 4/32 inch
RR Tires - 4/32 inch	Rain Sensor	Rear AC
Rear Defrost	Rear View Mirror	Reverse Camera
Seat Trim - Cloth	Side Airbags - Front	Steering Wheel Audio Control
Tilt Steering Wheel	Tilt Wheel	Tire Brand - Front Left - Hood
Tire Brand - Front Left - LF tire mfg Goodyear	Tire Brand - Front Right - RF tire mfg Goodyear	Tire Brand - Rear Left - LR tire mfg Goodyear
Tire Brand - Rear Right - RR tire mfg Goodyear	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Two-Wheel Drive	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
Chargeable Damages				
Photo	Item	Damage	Action	Severity
[no photo]	Hood	Chipped	Repair	10 Or More

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Cargo Box Left Side Wall	Multiple Dents/No Paint Damage	Repair	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.