



Approved CR

IAA Houston South
2839 E FM 1462
Branch No 414
Rosharon, TX 77583
(281)369-1010/(833)246-9256
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
TRANSIT
CONNECT**

Bodystyle/Series: **Wagon XL
PASSENGER**

Color: **Blue**

Mileage: **70,506
(Verified)**

Turn-in Mileage: **-**

VIN: **NM0GE9E22L1460707**

Work Order/
Stock Number: **46235422**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G41-5495W**

Vehicle Grade : **Grade 3.2**

Remarks: **-**

Announcements:

- Active Codes

See IAA
Condition
Report

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 215 / 55 R 16	Car Tire Size - LR 215 / 55 R 16	Car Tire Size - RR 215 / 55 R 16
Car Tire Size - RF 215 / 55 R 16	LF Tires - 9/32 inch	LR Tires - 9/32 inch
RF Tires - 9/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - SUREDRIVE
Tire Brand - Front Right - SUREDRIVE	Tire Brand - Rear Left - SUREDRIVE	Tire Brand - Rear Right - SUREDRIVE
Tire Model - LR - All-Season	Tire Model - LF - All-Season	Tire Model - RF - All-Season
Tire Model - RR - All-Season		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Windshield	Replaced	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
-------	------	--------	--------	----------

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Right Front Wheel Cover	Missing	-	Replacement Required
	Right Rear Wheel Cover	Missing	-	Replacement Required
	Left Qtr Panel	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Lift Gate	Dent(S) W/ Paint Dmg	-	7 To 8 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel Cover	Missing	-	Replacement Required
	Left Front Wheel Cover	Missing	-	Replacement Required
	Left Front Fender	Heavy Scratch	-	1 To 2 Inches
	Steering Wheel	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.