



Approved CR

IAA Anchorage
1446 W Mystery Ave
Branch No 372
Wasilla, AK 99654
(907)312-5580/(907)312-5680
WHOLESALE ASSESSMENT ONLY

Make/Model: **2022 FORD
F-250**
Bodystyle/Series: **Crew Cab XL**
Color: **Gold**
Mileage: **83,306
(Verified)**
Turn-in Mileage: **-**
VIN: **1FT7W2B61NED61709**
Work Order/
Stock Number: **46312414**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G631442Y**
Vehicle Grade : **Grade 3.8**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment


Additional Equipment:

Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RR 265 / 70 R 17
Car Tire Size - RF 265 / 70 R 17	LF Tires - 5/32 inch	LR Tires - 5/32 inch
RF Tires - 5/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - KENDA
Tire Brand - Front Right - KENDA	Tire Brand - Rear Left - KENDA	Tire Brand - Rear Right - KENDA
Tire Model - RR - Klever A/T2 (KR628)	Tire Model - RF - Klever A/T2 (KR628)	Tire Model - LR - Klever A/T2 (KR628)
Tire Model - LF - Klever A/T2 (KR628)		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof Luggage Rack	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	2
	Right Front Wheel	Corrosion	-	9 To 10 Inches
	Right Rear Wheel	Corrosion	-	9 To 10 Inches
	Rear Metal Bumper Painted	Chipped	-	3
	Left Rear Wheel	Corrosion	-	3 To 4 Inches
	Left Front Wheel	Corrosion	-	7 To 8 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Tailgate	Dent(S) W/ Paint Dmg	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.