Approved CR

IAA San Diego
2380 Britannia Blvd
Branch No 116
San Diego, CA 92154
(619) 710-2866/(619) 710-2878
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 DODGE GRAND CARAVAN**
Bodystyle/Series:	**Van SE**
Color:	**White**
Mileage:	**16,389 (Verified)**
Turn-in Mileage:	-
VIN:	**2C4RDGBG4HR725911**
Work Order/ Stock Number:	**46417392**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G410675U**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	• WARNING INDICATOR LIGHT ON (SEE IAA CONDITION REPORT FOR DETAILS)
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**Front Wheel Drive**

Equipment

Seat Count: -

Brakes: **Disc**

Additional Equipment:

Car Tire Size - RR 225 / 65 R 17	Car Tire Size - RF 225 / 65 R 17	Car Tire Size - LF 225 / 65 R 17
Car Tire Size - LR 225 / 65 R 17	LF Tires - 9/32 inch	LR Tires - 8/32 inch
RF Tires - 9/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - KENDA
Tire Brand - Front Right - KENDA	Tire Brand - Rear Left - MOHAVE	Tire Brand - Rear Right - MOHAVE
Tire Model - RR - Mohave Cuv	Tire Model - RF - Kenetica Touring A/S KR217	Tire Model - LR - Mohave Cuv
Tire Model - LF - Kenetica Touring A/S KR217		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel Cover	Broken	-	Replacement Required
	Left Qtr Panel	Rust	-	1 To 2 Inches
	Right Front Fender	Heavy Scratch	-	3 To 4 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Rear Bumper	Heavy Scratch	-	1 To 2 Inches
	Front Bumper	Heavy Scratch	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.