



Approved CR

IAA Oklahoma City
7300 N 1-35 Service RD
Branch No 421
Oklahoma City, OK 73121
(405) 475-0230/(405) 680-9204
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019
HYUNDAI
ELANTRA**

Bodystyle/Series: **4 Door Sedan
SE**

Color: **Blue**

Mileage: **64,710
(Verified)**

Turn-in Mileage: **-**

VIN: **5NPD74LF5KH487447**

Work Order/
Stock Number: **46358111**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G131045W**

Vehicle Grade : **Grade 3.3**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment



Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 195 / 65 R 15	Car Tire Size - LR 195 / 65 R 15	Car Tire Size - RR 195 / 65 R 15
Car Tire Size - RF 195 / 65 R 15	LF Tires - 7/32 inch	LR Tires - 7/32 inch
RF Tires - 9/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - MASTERCRAFT
Tire Brand - Front Right - MASTERCRAFT	Tire Brand - Rear Left - MASTERCRAFT	Tire Brand - Rear Right - MASTERCRAFT
Tire Model - RR - Stratus As	Tire Model - RF - Stratus As	Tire Model - LR - Stratus As
Tire Model - LF - Stratus As		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Deck Lid	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Hood	Peeling	-	1/2 To 1 Inch
	Right Drip Rail	Dent(S) W/ Paint Dmg	-	1/8 To 1/2 Inch
	Rear Bumper	Dent(S) W/ Paint Dmg	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Headlining	Stained	-	Permanent
	Left Head Lamp	Faded	-	Repair Required
	Right Rear Wheel Cover	Curb Rash	-	5 To 6 Inches
	Roof	Multiple Dents/Paint Damage	-	3
	Front Bumper Cover Upper	Heavy Scratch	-	4 To 5 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.