



Approved CR

IAA Baton Rouge
5978 Hwy 75
Branch No 422
Carville, LA 70721
(225) 686-9197/(225) 686-8197
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
FUSION**
Bodystyle/Series: **4 Door Sedan
HYBRID SE**
Color: **Silver**
Mileage: **127,241
(Verified)**
Turn-in Mileage: **-**
VIN: **3FA6P0LU7LR200596**
Work Order/
Stock Number: **46358470**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G100895X**
Vehicle Grade : **Grade 4.0**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	No
Engine Size:	2 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /-	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 60 R 17	Car Tire Size - LR 225 / 60 R 17	Car Tire Size - RR 225 / 60 R 17
Car Tire Size - RF 225 / 60 R 17	LF Tires - 5/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - FALKEN
Tire Brand - Front Right - FALKEN	Tire Brand - Rear Left - FALKEN	Tire Brand - Rear Right - FALKEN
Tire Model - RR - Ziex ZE960 A/S	Tire Model - RF - Ziex ZE960 A/S	Tire Model - LR - Ziex ZE960 A/S
Tire Model - LF - Ziex ZE960 A/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	10 Or More

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	> 12 Inches
	Rear Bumper	Chipped	-	1
	Left Rear Wheel	Curb Rash	-	1 To 2 Inches
	Windshield	Cracked	-	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.