



Approved CR

IAA Baton Rouge  
5978 Hwy 75  
Branch No 422  
Carville, LA 70721  
(225) 686-9197/(225) 686-8197  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018  
HYUNDAI  
IONIQ  
HYBRID**

Bodystyle/Series: **4 Door Hatch  
Back BLUE**

Color: **White**

Mileage: **70,206  
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHC65LC5JU100423**

Work Order/  
Stock Number: **46358355**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**

Client Stock #: **G131447V**

Vehicle Grade : **Grade 3.8**

Remarks: **-**

Announcements: 

- Active Codes

see IAA  
Condition  
Report

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

### Equipment

|                        |                   |                 |                   |
|------------------------|-------------------|-----------------|-------------------|
| Transmission:          | -                 | A/C:            | No                |
| Engine:                | 4-Cylinder Hybrid | Cruise Control: | No                |
| Engine Size:           | 1.6 L             | Pwr Steering:   | No                |
| Roof:                  | -                 | Pwr Locks:      | No                |
| Radio:                 | -                 | Pwr Windows     | No                |
| Interior - Type/Color: | - /-              | Rear Defroster: | No                |
| Airbag:                | -                 | Tilt Steering:  | No                |
| Seats:                 | -                 | Drive Type:     | Front Wheel Drive |
| Seat Count:            | -                 | Brakes:         | -                 |

## Equipment

### Additional Equipment:

Car Tire Size - LR 195 / 65 R 15

Car Tire Size - RR 195 / 65 R 15

Car Tire Size - RF 195 / 65 R 15

Car Tire Size - LF 195 / 65 R 15

LF Tires - 8/32 inch

LR Tires - 9/32 inch

RF Tires - 9/32 inch

RR Tires - 10/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - LF - All Season

Tire Model - LR - All Season

Tire Model - RF - All Season

Tire Model - RR - All Season

## Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Rear Seats              | Photo Only | -      | -        |
|    | Rear Bumper             | Photo Only | -      | -        |
|   | Odometer                | Photo Only | -      | -        |
|  | Extra Photo 1           | Photo Only | -      | -        |
|  | Photo - Dash            | Photo Only | -      | -        |
|  | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|  | Left Front Fender       | Photo Only | -      | -        |

| Non Chargeable Damages                                                              |                        |            |        |          |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
| Photo                                                                               | Item                   | Damage     | Action | Severity |
|    | Right Front Fender     | Photo Only | -      | -        |
|    | Instrument Panel       | Photo Only | -      | -        |
|    | Left Side Panel        | Photo Only | -      | -        |
|    | Right Side Panel       | Photo Only | -      | -        |
|    | Front Cover Center     | Photo Only | -      | -        |
|   | Keys                   | Photo Only | -      | -        |
|  | Engine                 | Photo Only | -      | -        |
|  | Photo - Vin/Id Sticker | Photo Only | -      | -        |

| Chargeable Damages                                                                  |      |         |        |               |
|-------------------------------------------------------------------------------------|------|---------|--------|---------------|
| Photo                                                                               | Item | Damage  | Action | Severity      |
|  | Roof | Peeling | -      | 3 To 4 Inches |

| Chargeable Damages                                                                  |                            |               |        |                 |
|-------------------------------------------------------------------------------------|----------------------------|---------------|--------|-----------------|
| Photo                                                                               | Item                       | Damage        | Action | Severity        |
|    | Left Rear Wheel Cover      | Curb Rash     | -      | 1 To 2 Inches   |
|    | Rear Bumper                | Heavy Scratch | -      | 7 To 8 Inches   |
|    | Right Rocker Panel Molding | Scuffed       | -      | > 12 Inches     |
|   | Right Head Lamp            | Faded         | -      | Repair Required |
|  | Left Head Lamp             | Faded         | -      | Repair Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.