



Approved
CR

IAA Baton Rouge
5978 Hwy 75
Branch No 422
Carville, LA 70721
(225) 686-9197/(225) 686-8197
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 RAM
3500**
Bodystyle/Series: **Crew Cab
TRADESMAN**
Color: **Black**
Mileage: **36,048
(Verified)**
Turn-in Mileage: **-**
VIN: **3C63R3GT5GG335191**
Work Order/
Stock Number: **46358274**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G630513S**
Vehicle Grade : **Grade 3.0**
Remarks: **-**
Announcements:

- Active Codes
see IAA
Condition
Report;
Windshield
cracked

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 275 / 70 R 18	Car Tire Size - LR 275 / 70 R 18	Car Tire Size - RR 275 / 70 R 18
Car Tire Size - RF 275 / 70 R 18	LF Tires - 4/32 inch	LR Tires - 7/32 inch
RF Tires - 3/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - wrangler	Tire Model - RF - wrangler	Tire Model - LR - wrangler
Tire Model - LF - wrangler		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Bed Side	Dent(S) W/ Paint Dmg	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Tailgate	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Left Bed Side	Dent(S) W/ Paint Dmg	-	4 To 5 Inches
	Left Front Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Windshield	Cracked	-	> 12 Inches
	Right Front Tire	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate Protective Cap	Missing	-	Replacement Required
	Inside Bed	Heavy Scratch	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.