



Approved CR

IAA Baton Rouge
5978 Hwy 75
Branch No 422
Carville, LA 70721
(225) 686-9197/(225) 686-8197
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
CHEVROLET
MALIBU**

Bodystyle/Series: **4 Door Sedan
FWD 1FL**

Color: **White**

Mileage: **65,003
(Verified)**

Turn-in Mileage: **-**

VIN: **1G1ZC5ST2LF137521**

Work Order/
Stock Number: **46358189**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G102773X**

Vehicle Grade : **Grade 3.8**

Remarks: **-**

Announcements:

- Active Codes

see IAA
Condition
Report

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	1.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 205 / 65 R 16

Car Tire Size - RF 205 / 65 R 16

Car Tire Size - LF 205 / 65 R 16

Car Tire Size - LR 205 / 65 R 16

LF Tires - 9/32 inch

LR Tires - 8/32 inch

RF Tires - 8/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - LF - All Season

Tire Model - LR - All Season


Tire Model - RF - All Season

Tire Model - RR - All Season

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Steering Wheel	Worn	-	Acceptable

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	3
	Front Bumper	Chipped	-	3
	Left Front Wheel	Curb Rash	-	1 To 2 Inches
	Left Qtr Panel	Chipped	-	2
	Rear Bumper	Multiple Scratches Heavy	-	3
	Right Rear Wheel	Curb Rash	-	7 To 8 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rocker Panel	Multiple Scratches Heavy	-	3
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.