Approved CR

IAA San Diego
2380 Britannia Blvd
Branch No 116
San Diego, CA 92154
(619) 710-2866/(619) 710-2878
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2023 FORD POLICE INTERCEPTOR**
Bodystyle/Series:	**Sport Utility Vehicle -**
Color:	**White**
Mileage:	**134,040 (Verified)**
Turn-in Mileage:	-
VIN:	**1FM5K8AB2PGB11239**
Work Order/ Stock Number:	**46179052**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G62A1610**
Vehicle Grade :	**Grade 3.4**
Remarks:	-
Announcements:	• CONDITION UNKNOWN • FORMER POLICE VEHICLE • SALVAGE STAMPED CERTIFICATE TO OBTAIN TITLE WILL BE ISSUED • REAR DOORS / WINDOWS INOPERABLE MAY BE INOPERABLE • REPAIRS MAYBE NEEDED. • PARTS MAYBE MISSING
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**All Wheel Drive**
Seat Count:	-	Brakes:	**Disc**


Additional Equipment:

Car Tire Size - LF 255 / 60 R 18	Car Tire Size - LR 255 / 60 R 18	Car Tire Size - RR 255 / 60 R 18
Car Tire Size - RF 255 / 60 R 18	LF Tires - 6/32 inch	LR Tires - 6/32 inch
RF Tires - 6/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - BRIDGESTONE
Tire Model - RR - Alenza 001	Tire Model - RF - Firehawk Pursuit Awt	Tire Model - LR - Firehawk Pursuit Awt
Tire Model - LF - Firehawk Pursuit Awt		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Drip Rail	Previous Repair	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Previous Repair	-	Acceptable
	Center Console	Aftermarket	-	Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Windshield	Multiple Chips	-	2
	Steering Wheel	Worn	-	Replacement Required
	Overall Vehicle	De-Identify	-	Removal Required
	Right Rear Wheel	Chipped	-	6

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Multiple Scratches Heavy	-	6
	Left Front Seat Molding	Loose	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.