



Approved
CR

IAA Detroit
8251 Rawsonville Road
Branch No 516
Belleville, MI 48111
(734) 461-9441/(734) 461-9419
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 JEEP
GRAND
CHEROKEE**
Bodystyle/Series: **Sport Utility
Vehicle
LAREDO E 4X4**
Color: **Gray**
Mileage: **77,178 (Verified)**
Turn-in Mileage: **-**
VIN: **1C4RJFAG1KC828269**
Work Order/
Stock Number: **46054709**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G625901W**
Vehicle Grade : **Grade 4.3**
Remarks: **-**
Announcements:

**• LAW
ENFORCEMENT
USE**

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 70 R 17

Car Tire Size - RR 245 / 70 R 17

Car Tire Size - LR 245 / 70 R 17

Car Tire Size - RF 245 / 70 R 17

LF Tires - 7/32 inch

LR Tires - 6/32 inch

RF Tires - 7/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - GOODYEAR

Tire Brand - Front Right - GOODYEAR

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - GOODYEAR

Tire Model - LF - Fortera HL

Tire Model - LR - Fortera HL

Tire Model - RF - Fortera HL

Tire Model - RR - Fortera HL

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	1

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.