



Approved CR

IAA Las Vegas
3225 South Hollywood Blvd
Branch No 152
Las Vegas, NV 89122
(702) 565-8795/(702) 564-6553
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
F-450**
Bodystyle/Series: **Crew Cab XL**
Color: **White**
Mileage: **85,045
(Verified)**
Turn-in Mileage: **-**
VIN: **1FT8W4DT5HEE15052**
Work Order/
Stock Number: **46272069**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G710728U**
Vehicle Grade : **Grade 4.5**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Air Brakes

Equipment


Additional Equipment:

Car Tire Size - LF 225 / 70 R 19.5	Car Tire Size - LR 225 / 70 R 19.5	Car Tire Size - RR 225 / 70 R 19.5
Car Tire Size - RF 225 / 70 R 19.5	LF Tires - 12/32 inch	LR Tires - 16/32 inch
RF Tires - 12/32 inch	RR Tires - 16/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - G622 RSD	Tire Model - RF - Endurance Rsa	Tire Model - LR - G622 RSD
Tire Model - LF - Endurance Rsa		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Tailgate	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.