



Approved
CR

IAA Providence
160 Amaral St
Branch No 644
Riverside, RI 02915
(401) 438-5254/(401) 438-3523
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023 DODGE
CHARGER**
Bodystyle/Series: **4 Door Sedan
POLICE AWD**
Color: **Black**
Mileage: **47,884 (Verified)**
Turn-in Mileage: **-**
VIN: **2C3CDXKG3PH675629**
Work Order/
Stock Number: **46416877**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G11A0813**
Vehicle Grade : **Grade 1.4**
Remarks: **-**
Announcements:

- ANNOUNCEMENTS:
Prior Law
Enforcement/
SALVAGE

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: No

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 60 R 18

Car Tire Size - RF 225 / 60 R 18

Car Tire Size - LR 225 / 60 R 18

Car Tire Size - LF N/A / N/A R N/A

LR Tires - 6/32 inch

RF Tires - 9/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - Missing

Tire Brand - Front Right - Unknown

Tire Brand - Rear Left - Unknown

Tire Brand - Rear Right - Unknown

Tire Model - RR - Unknown

Tire Model - RF - Unknown

Tire Model - LR - Unknown

Tire Model - LF - Missing

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Seat Center Rear	Worn	-	Acceptable
	Left Apron	Kinked	-	> 12 Inches
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Windshield	Pitted	-	Replacement Required
	Left Rocker Panel Molding	Dent(S) W/ Paint Dmg	-	Replacement Required
	Right Front Wheel	Bent	-	Replacement Required
	Hood	Heavy Scratch	-	1/8 To 1/2 Inch
	Left Front Wheel	Broken	-	Replacement Required
	Lf Axle Assembly	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Broken	-	Replacement Required
	Front Bumper	Broken	-	Replacement Required
	Left Front Fender	Severe Damage	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.