



Approved CR

IAA Atlanta West  
1871 Rome Hwy  
Branch No 793  
Rockmart, GA 30153  
(470) 598-3740  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2022 CHRYSLER VOYAGER**  
Bodystyle/Series: **Van LX**  
Color: **Silver**  
Mileage: **110,170 (Verified)**  
Turn-in Mileage: **-**  
VIN: **2C4RC1CGXNR141569**  
Work Order/ Stock Number: **46356693**  
Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**  
Client Stock #: **G413282Y**  
Vehicle Grade : **Grade 3.1**  
Remarks: **-**  
Announcements: **-**  
Certification : **-**  
Req. Prev. Repair Order: **-**



Drivable: Yes

### Equipment


|                        |                               |                 |                          |
|------------------------|-------------------------------|-----------------|--------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>No</b>                |
| Engine:                | <b>6-Cylinder Flex Fuel</b>   | Cruise Control: | <b>Yes</b>               |
| Engine Size:           | <b>3.6 L</b>                  | Pwr Steering:   | <b>Yes</b>               |
| Roof:                  | <b>Carriage</b>               | Pwr Locks:      | <b>Yes</b>               |
| Radio:                 | <b>-</b>                      | Pwr Windows     | <b>Yes</b>               |
| Interior - Type/Color: | <b>Cloth/Vinyl /BLACK</b>     | Rear Defroster: | <b>Yes</b>               |
| Airbag:                | <b>Driver Side Air Bag</b>    | Tilt Steering:  | <b>Yes</b>               |
| Seats:                 | <b>3rd</b>                    | Drive Type:     | <b>Front Wheel Drive</b> |
| Seat Count:            | <b>-</b>                      | Brakes:         | <b>Disc</b>              |

## Equipment

### Additional Equipment:

|                                      |                                   |                                     |
|--------------------------------------|-----------------------------------|-------------------------------------|
| Car Tire Size - LF 235 / 65 R 17     | Car Tire Size - LR 235 / 65 R 17  | Car Tire Size - RR 235 / 65 R 17    |
| Car Tire Size - RF 235 / 65 R 17     | LF Tires - 7/32 inch              | LR Tires - 4/32 inch                |
| RF Tires - 5/32 inch                 | RR Tires - 3/32 inch              | Tire Brand - Front Left - FIRESTONE |
| Tire Brand - Front Right - FIRESTONE | Tire Brand - Rear Left - YOKOHAMA | Tire Brand - Rear Right - YOKOHAMA  |
| Tire Model - RR - Avid S34B          | Tire Model - RF - Destination LE3 | Tire Model - LR - Avid S34B         |
| Tire Model - LF - Destination LE3    |                                   |                                     |

## Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity     |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|--------------|
|    | Warning - Tire Pressure | On         | -      | Unacceptable |
|   | Photo - Vin/Id Sticker  | Photo Only | -      | -            |
|  | Engine                  | Photo Only | -      | -            |
|  | Keys                    | Photo Only | -      | -            |
|  | Front Cover Center      | Photo Only | -      | -            |
|  | Right Side Panel        | Photo Only | -      | -            |
|  | Left Side Panel         | Photo Only | -      | -            |

### Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Instrument Panel        | Photo Only | -      | -        |
|    | Rear Bumper             | Photo Only | -      | -        |
|    | Extra Photo 2           | Photo Only | -      | -        |
|    | Extra Photo 3           | Photo Only | -      | -        |
|    | Right Front Fender      | Photo Only | -      | -        |
|   | Extra Photo 4           | Photo Only | -      | -        |
|  | Extra Photo 5           | Photo Only | -      | -        |
|  | Extra Photo 6           | Photo Only | -      | -        |
|  | Left Front Fender       | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|  | Right Rear Bumper/Cover | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                             | Item          | Damage     | Action | Severity |
|-----------------------------------------------------------------------------------|---------------|------------|--------|----------|
|  | Photo - Dash  | Photo Only | -      | -        |
|  | Extra Photo 1 | Photo Only | -      | -        |
|  | Odometer      | Photo Only | -      | -        |
|  | Rear Seats    | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item             | Damage                      | Action | Severity        |
|-------------------------------------------------------------------------------------|------------------|-----------------------------|--------|-----------------|
|   | Windshield       | Chipped                     | -      | 1/8 To 1/2 Inch |
|  | Right Front Door | Dent(S) W/ Paint Dmg        | -      | 2 To 3 Inches   |
|  | Right Rear Door  | Multiple Dents/Paint Damage | -      | 2               |

### Chargeable Damages

| Photo                                                                               | Item              | Damage                   | Action | Severity             |
|-------------------------------------------------------------------------------------|-------------------|--------------------------|--------|----------------------|
|    | Right Qtr Panel   | Dent(S) W/ Paint Dmg     | -      | 3 To 4 Inches        |
|    | Right Rear Tire   | Worn                     | -      | Replacement Required |
|    | Rear Bumper       | Multiple Scratches Heavy | -      | 2                    |
|   | Front Bumper      | Dent(S) W/ Paint Dmg     | -      | 5 To 6 Inches        |
|  | Left Front Fender | Heavy Scratch            | -      | 1/2 To 1 Inch        |
|  | Roof              | Chipped                  | -      | 2                    |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.