



Approved CR

IAA Atlanta West
1871 Rome Hwy
Branch No 793
Rockmart, GA 30153
(470) 598-3740
WHOLESALE ASSESSMENT ONLY

Make/Model: **2022 CHRYSLER VOYAGER**
Bodystyle/Series: **Van LX**
Color: **Silver**
Mileage: **82,992 (Verified)**
Turn-in Mileage: **-**
VIN: **2C4RC1CG7NR141531**
Work Order/
Stock Number: **46356692**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G413273Y**
Vehicle Grade : **Grade 3.6**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 17

Car Tire Size - LR 235 / 65 R 17

Car Tire Size - RR 235 / 65 R 17

Car Tire Size - RF 235 / 65 R 17

LF Tires - 6/32 inch

LR Tires - 9/32 inch

RF Tires - 6/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - YOKOHAMA

Tire Brand - Front Right - YOKOHAMA

Tire Brand - Rear Left - YOKOHAMA

Tire Brand - Rear Right - YOKOHAMA

Tire Model - RR - Avid S34B

Tire Model - RF - Avid S34B

Tire Model - LR - Avid S34B

Tire Model - LF - Avid S34B

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Right Front Door Handle	Heavy Scratch	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rocker Panel Molding	Multiple Scratches Heavy	-	5
	Front Bumper	Chipped	-	6
	Right Front Wheel	Curb Rash	-	6 To 7 Inches
	Right Rear Door	Chipped	-	1

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Lift Gate	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Left Qtr Panel	Dent(S) W/No Paint Dmg	-	2 To 3 Inches
	Left Rear Wheel	Curb Rash	-	1 To 2 Inches
	Left Front Wheel	Curb Rash	-	2 To 3 Inches
	Left Front Fender	Multiple Scratches Light	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.