



Approved CR

IAA Atlanta West
1871 Rome Hwy
Branch No 793
Rockmart, GA 30153
(470) 598-3740
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 DODGE
GRAND
CARAVAN**

Bodystyle/Series: **Van SE**

Color: **Silver**

Mileage: **97,397
(Verified)**

Turn-in Mileage: **-**

VIN: **2C4RDGBG7KR676520**

Work Order/
Stock Number: **46356690**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G411230W**

Vehicle Grade : **Grade 3.2**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 65 R 17

Car Tire Size - RF 225 / 65 R 17

Car Tire Size - LF 225 / 65 R 17

Car Tire Size - LR 225 / 65 R 17

LF Tires - 4/32 inch

LR Tires - 7/32 inch

RF Tires - 7/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - MOHAVE

Tire Brand - Front Right - MOHAVE

Tire Brand - Rear Left - MOHAVE

Tire Brand - Rear Right - MOHAVE

Tire Model - RR - Mohave Cuv

Tire Model - RF - Mohave Cuv

Tire Model - LR - Mohave Cuv

Tire Model - LF - Mohave Cuv

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Right Rear Wheel Cover	Curb Rash	-	4 To 5 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Chipped	-	2
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel Cover	Curb Rash	-	2 To 3 Inches
	Front Bumper	Cracked	-	2 To 3 Inches
	Lift Gate	Multiple Scratches Heavy	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.