



Approved
CR

United Auto Exchange
3710 Prescott Rd
Memphis, TN 38118
9017957634
jcraig@uaxmemphis.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
FUSION
4 Door Vehicle**
Bodystyle/Series: **HYBRID SE
4D SEDAN**
Color: **WHITE**
Mileage: **62,621
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **3FA6P0LU0LR231429**
Work Order/
Stock Number: **000084540**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G101551X**
Vehicle Grade : **Grade 4.6**
Remarks: **-**

Announcements:

• DEFICIENCIES,
WHEN
KNOWN,
HAVE BEEN
NOTED IN THE
ITEM
DESCRIPTION
• HOWEVER,
THE ABSENCE
OF ANY
INDICATED
DEFICIENCIES
• DOES NOT
MEAN THERE
ARE NONE.

Certification : **Not Certified**
Req. Prev. Repair
Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission: **Automatic Transmission** A/C: **Yes**

Equipment			
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	Power	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
4th Passenger Door	ABS Brakes	Adaptive Cruise Control	
Air Conditioning	Automatic Headlights	Auxiliary Pwr Outlet	
Blind Spot Monitor	Bluetooth Connection	Brake Assist System	
Car Tire Size - RR tire size 225/60R17	Car Tire Size - LR tire size 225/60R17	Car Tire Size - LF tire size 225/60R17	
Car Tire Size - RF tire size 225/60R17	Child Safety Locks	Cruise Control	
Cylinders - 4	Daytime Running Lights	Driver Air Bag	
Dual Air Conditioning	Electrochromic Rearview Mirror	Empty Weight - 3695 lb	
Engine Immobilizer	Floor Mats	Front Wheel Drive	
Front Wheel Drive	Independent Climate Control	Intermittent Wipers	
Keyless Entry	Keyless Start	LF Tires - 7/32 inch	
LR Tires - 6/32 inch	Lane Departure System	Master Key - 1key(s)	
Motor Fuel Type - Other	Navigation System	Pass-Through Rear Seat	
Pass. Air Bag	Power Brakes	Power Driver Seat	
Power Lock	Power Mirrors	Power Steering	
Power Trunk/Liftgate	Power Windows	Privacy Glass	
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Rain Sensor	
Rear Defrost	Rear Parking Aid	Remote Trunk Release	
Reverse Camera	Seat Trim - Cloth	Security System	
Side Airbags - Front	Steering Wheel Audio Control	Telematics	
Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg GOOD YEAR	Tire Brand - Front Right - RF tire mfg GOOD YEAR	
Tire Brand - Rear Left - LR tire mfg GOOD YEAR	Tire Brand - Rear Right - RR tire mfg GOOD YEAR	Tire Pressure Monitor System	
Traction Control	Transmission - Automatic Transmission w/ Overdrive	Trip Computer	
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium	
Wheels Rear Right - Aluminium			

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Frame	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	Touch Up	5
	Right Qtr Panel	Dent(S) W/No Paint Dmg	PDR	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Fender	Chipped	Touch Up	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.