



Approved CR

IAA Macon
2200 Trade Ave.
Branch No 734
Macon, GA 31217
(478) 314-0031/(478) 314-0040
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
F-250**
Bodystyle/Series: **Regular Cab
XL**
Color: **Gray**
Mileage: **44,572
(Verified)**
Turn-in Mileage: **-**
VIN: **1FDBF2A66JEC69478**
Work Order/
Stock Number: **46412909**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G430643V**
Vehicle Grade : **Grade 1.7**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

LF Tires - 6/32 inch

LR Tires - 3/32 inch

RF Tires - 4/32 inch

RR Tires - 3/32 inch

Tire Brand - Front Left - BLACKHAWK

Tire Brand - Front Right - BLACKHAWK

Tire Brand - Rear Left - BLACKHAWK

Tire Brand - Rear Right - BLACKHAWK

Tire Model - RR - Hiscend-H HT01

Tire Model - RF - Hiscend-H HT01


Tire Model - LR - Hiscend-H HT01

Tire Model - LF - Hiscend-H HT01

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable
	Warning Light - Engine	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	4
	Right Front Wheel	Curb Rash	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches
	Right Rear Tire	Worn	-	Replacement Required
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	6 To 7 Inches
	Tailgate	Chipped	-	8
	Exterior Rear Body Panel	Chipped	-	3
	Left Rear Wheel	Curb Rash	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Curb Rash	-	2 To 3 Inches
	Roof	Chipped	-	3
	Steering Wheel	Worn	-	Replacement Required
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Left Rear Tire	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.