



Approved CR

IAA Denver East
8510 Brighton Rd.
Branch No 374
Commerce City, CO 80022
(303) 287-9737/(303) 287-1214
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
F-350
CHASSIS**

Bodystyle/Series: **Crew Cab XL**

Color: **White**

Mileage: **43,688
(Verified)**

Turn-in Mileage: **-**

VIN: **1FD8W3H62GEC86731**

Work Order/
Stock Number: **46266204**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G632389S**

Vehicle Grade : **Grade 2.9**

Remarks: **-**

Announcements:

**• HAIL
DAMAGE**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

LF Tires - 6/32 inch

LR Tires - 6/32 inch

RF Tires - 4/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - ARGUS
ADVANTA

Tire Brand - Front Right - ARGUS
ADVANTA

Tire Brand - Rear Left - ARGUS
ADVANTA

Tire Brand - Rear Right - ARGUS
ADVANTA

Tire Model - LF - HTR-800

Tire Model - LR - HTR-800


Tire Model - RF - HTR-800

Tire Model - RR - HTR-800

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Frame	Rust	-	Naaa Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	> 12 Inches
	Left Front Wheel	Curb Rash	-	> 12 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Roof Panel	Hail Damage	-	10 Or More
	Hood	Hail Damage	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.