



Approved
CR

IAA El Paso
14751 Marina Ave
Branch No 420
El Paso, TX 79938
(915)852-2489/(915)852-2235
WHOLESALE ASSESSMENT ONLY

Make/Model: **2014 RAM 4500 CHASSIS**
Bodystyle/Series: **- TRADESMAN/SLT**
Color: **White**
Mileage: **51,863 (Verified)**
Turn-in Mileage: **-**
VIN: **3C7WRKBL0EG269575**
Work Order/
Stock Number: **46266113**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G710446Z**
Vehicle Grade : **Grade 1.9**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 70 R 19

Car Tire Size - LR 225 / 70 R 19

Car Tire Size - RR 225 / 70 R 19

Car Tire Size - RF 225 / 70 R 19

LF Tires - 11/32 inch

LR Tires - 11/32 inch

RF Tires - 11/32 inch

RR Tires - 12/32 inch

Tire Brand - Front Left - IRONMAN

Tire Brand - Front Right - IRONMAN

Tire Brand - Rear Left - IRONMAN

Tire Brand - Rear Right - IRONMAN

Tire Model - LF - I-109

Tire Model - RR - I-109

Tire Model - RF - I-109

Tire Model - LR - I-109

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Side Panel	Multiple Scratches Heavy	-	10 Or More
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Rust	-	> 12 Inches
	Left Side Panel	Multiple Scratches Heavy	-	10 Or More
	Left Rear Wheel	Curb Rash	-	2 To 3 Inches
	Left Front Wheel	Corrosion	-	9 To 10 Inches
	Left Drip Rail	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.