Approved
CR

IAA Denver East
8510 Brighton Rd.
Branch No 374
Commerce City, CO 80022
(303) 287-9737/(303) 287-1214
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 CHEVROLET TAHOE**
Bodystyle/Series:	**Sport Utility Vehicle LS**
Color:	**White**
Mileage:	**83,298 (Verified)**
Turn-in Mileage:	-
VIN:	**1GNSKAECXHR286871**
Work Order/ Stock Number:	**46404021**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G620314U**
Vehicle Grade :	**Grade 3.2**
Remarks:	-
Announcements:	• MISSING CENTER CONSOLE • HOLE IN ROOF FROM AFTERMARKET ANTENNA
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**4-Wheel Drive**

Equipment

Seat Count: -

Brakes: **Disc**



Additional Equipment:

Car Tire Size - RR 265 / 65 R 18	Car Tire Size - LF 265 / 65 R 18	Car Tire Size - RF 265 / 65 R 18
Car Tire Size - LR 265 / 65 R 18	LF Tires - 11/32 inch	LR Tires - 11/32 inch
RF Tires - 11/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - HERCULES
Tire Brand - Front Right - HERCULES	Tire Brand - Rear Left - HERCULES	Tire Brand - Rear Right - HERCULES
Tire Model - RR - Terra Trac Cross-V Aw	Tire Model - RF - Terra Trac Cross-V Aw	Tire Model - LR - Terra Trac Cross-V Aw
Tire Model - LF - Terra Trac Cross-V Aw		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Multiple Dents/Paint Damage	-	3
	Front Bumper	Chipped	-	6
	Right Front Wheel	Curb Rash	-	9 To 10 Inches
	Right Front Door	Chipped	-	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Multiple Scratches Heavy	-	7
	Right Rear Wheel	Curb Rash	-	6 To 7 Inches
	Hitchplate Cover	Missing	-	Replacement Required
	Left Rear Wheel	Curb Rash	-	9 To 10 Inches
	Left Front Door	Dent(S) W/No Paint Dmg	-	1/2 To 1 Inch
	Left Front Wheel	Curb Rash	-	7 To 8 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Rust	-	2 To 3 Inches
	Windshield	Chipped	-	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.