



Approved CR

IAA Elkton
183 Zeitler Rd
Branch No 786
Elkton, MD 21921
(410) 695-4477
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021 NISSAN SENTRA**
Bodystyle/Series: **4 Door Sedan S XTRONIC CVT**
Color: **Silver**
Mileage: **91,201 (Verified)**
Turn-in Mileage: **-**
VIN: **3N1AB8BV6MY270886**
Work Order/
Stock Number: **46416316**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **g131677y**
Vehicle Grade : **Grade 3.2**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 205 / 60 R 16

Car Tire Size - RF 205 / 60 R 16

Car Tire Size - LF 205 / 60 R 16

Car Tire Size - LR 205 / 60 R 16

LF Tires - 9/32 inch

LR Tires - 9/32 inch

RF Tires - 9/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - MAVIS

Tire Brand - Front Right - MAVIS

Tire Brand - Rear Left - MAVIS

Tire Brand - Rear Right - MAVIS

Tire Model - LF - All Season Highway
Touring

Tire Model - LR - All Season Highway
Touring

Tire Model - RF - All Season Highway
Touring

Tire Model - RR - All Season Highway
Touring

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Back	Cut	-	1/2 To 1 Inch
	Front Bumper	Heavy Scratch	-	> 12 Inches
	Right Front Door	Multiple Scratches Heavy	-	3
	Right Qtr Panel	Chipped	-	1

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Multiple Scratches Heavy	-	2
	Rear Bumper	Chipped	-	10 Or More
	Windshield	Pitted	-	Replacement Required
	Right Rocker Panel	Multiple Scratches Heavy	-	2
	Right Front Wheel Cover	Curb Rash	-	> 12 Inches
	Right Rear Wheel Cover	Curb Rash	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel Cover	Broken	-	Replacement Required
	Left Front Wheel Cover	Curb Rash	-	< 1/8 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.