



Approved CR

IAA Macon
2200 Trade Ave.
Branch No 734
Macon, GA 31217
(478) 314-0031/(478) 314-0040
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
TRANSIT-350
PASSENGER
VAN**

Bodystyle/Series: **Wagon XL**

Color: **Red**

Mileage: **130,343
(Verified)**

Turn-in Mileage: **-**

VIN: **1FBAX2Y82LKB08882**

Work Order/
Stock Number: **46039304**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G432349X**

Vehicle Grade : **Grade 2.4**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 235 / 65 R 16

Car Tire Size - RF 235 / 65 R 16

Car Tire Size - LF 235 / 65 R 16

Car Tire Size - LR 235 / 65 R 16

LF Tires - 11/32 inch

LR Tires - 7/32 inch

RF Tires - 10/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - LF - Transforce CV2

Tire Model - LR - Transforce CV2

Tire Model - RF - Transforce CV2

Tire Model - RR - Transforce CV2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Right Front Seat Back	Worn	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Cargo Door	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Rear Cargo Door	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Tail Light	Heavy Scratch	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right 3rd Row Carpet	Torn	-	> 12 Inches
	Right Rear Seat Cushion	Torn	-	2 To 3 Inches
	Headlining	Worn	-	Replacement Required
	Left Front Seat Cushion	Torn	-	2 To 3 Inches
	Steering Wheel	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.