Approved CR

IAA New Orleans East
6600 Almonaster Avenue
Branch No 432
New Orleans, LA 70126
(504) 240-2298/(504) 244-0883
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 FORD F-550 CHASSIS**
Bodystyle/Series:	**Regular Cab XL**
Color:	**White**
Mileage:	**62,930 (Verified)**
Turn-in Mileage:	-
VIN:	**1FDAF5GT1HEE87199**
Work Order/ Stock Number:	**46487010**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G320958U**
Vehicle Grade :	**Grade 2.8**
Remarks:	-
Announcements:	• active codes see iaa condition report
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Diesel**	Cruise Control:	**Yes**
Engine Size:	**6.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**5th**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 70 R 19	Car Tire Size - RF 225 / 70 R 19	Car Tire Size - LF 225 / 70 R 19
Car Tire Size - LR 225 / 70 R 19	LF Tires - 13/32 inch	LR Tires - 16/32 inch
RF Tires - 15/32 inch	RR Tires - 16/32 inch	Tire Brand - Front Left - IRONMAN
Tire Brand - Front Right - IRONMAN	Tire Brand - Rear Left - IRONMAN	Tire Brand - Rear Right - IRONMAN
Tire Model - LF - I-37D Gen 2	Tire Model - LR - gen	Tire Model - RF - gen
Tire Model - RR - gen		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Running Board	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Roof Panel	Peeling	-	> 12 Inches
	Right Front Fender	Chipped	-	2
	Rear Rs Panel Extension	Multiple Dents/Paint Damage	-	4
	Windshield	Cracked	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Rear Metal Bumper Painted	Multiple Scratches Heavy	-	4
	Front Rs Panel	Multiple Scratches Light	-	3
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Head Lamp	Faded	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Rear Wheel	Curb Rash	-	7 To 8 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.