



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD EXPLORER**
4 Door Sport Utility
Bodystyle/Series: **Vehicle BASE**
4WD 4D SUV
4WD
Color: **WHITE**
Mileage: **64,353**
(Verified, 6 digits)
Turn-in Mileage: **-**
VIN: **1FM5K8B86JGC57217**
Work Order/
Stock Number: **000354610**
Customer: **GSA Fleet Vehicle Sales**
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: **G622441V**
Vehicle Grade : **Grade 3.6**
Remarks: **REMOVAL**
OF POLICE
LIGHTS/ PA
SYSTEM
Announcements: **-**
Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	Power	Drive Type:	4-Wheel Drive

Equipment

Seat Count: -	Brakes:	Power Brakes
Additional Equipment:		
3rd Row Seat	4 Wheel Drive	4 Wheel Drive
4th Passenger Door	ABS Brakes	Air Conditioning
Automatic Headlights	Auxiliary Pwr Outlet	Bluetooth Connection
Brake Assist System	Car Tire Size - LF tire size P245/60HR18	Car Tire Size - LR tire size P245/60HR18
Car Tire Size - RR tire size P245/60HR18	Car Tire Size - RF tire size P245/60HR18	Child Safety Locks
Cruise Control	Cylinders - 6	Daytime Running Lights
Driver Air Bag	Empty Weight - 4629 lb	Engine Immobilizer
Floor Mats	Heated Mirrors	Independent Climate Control
Intermittent Wipers	Keyless Entry	LED Headlights
LF Tires - 7/32 inch	LR Tires - 8/32 inch	Master Key - 1key(s)
Motor Fuel Type - Gas	Pass-Through Rear Seat	Pass. Air Bag
Power Brakes	Power Driver Seat	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 6/32 inch	RR Tires - 7/32 inch
Rear AC	Rear Defrost	Rear Spoiler
Reverse Camera	Seat Trim - Cloth	Side Airbags - Front
Steering Wheel Audio Control	Telematics	Tilt Steering Wheel
Tire Brand - Front Left - LF tire mfg Firestone	Tire Brand - Front Right - RF tire mfg Firestone	Tire Brand - Rear Left - LR tire mfg Firestone
Tire Brand - Rear Right - RR tire mfg Firestone	Tire Pressure Monitor System	Tow Hitch
Traction Control	Transmission - Automatic Transmission w/ Overdrive	Trip Computer
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 10	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Seat	Stained	Report	Permanent
	Right Qtr Panel	Multiple Scratches Light	Report	3
	Hood	Chipped	Report	5
	Left Qtr Panel	Chipped	Report	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Multiple Dents/Paint Damage	Report	3
[no photo]	Battery	Inoperable	Report	Repair Required
	Rear Bumper	Chipped	Report	4
	Roof	Chipped	Report	4
	Right Front Door	Multiple Dents/No Paint Damage	Report	2
	Right Front Fender	Multiple Scratches Light	Report	4
	Right Front Mirror Housing	Multiple Scratches Light	Report	3
	Right Front Seat	Stained	Report	Permanent
	Right Rear Door	Enviro Paint Damage	Report	5 To 6 Inches
	Right Rear Seat	Stained	Report	Permanent
	Seat Center Rear	Stained	Report	Permanent
	3rd Row Seat	Stained	Report	Permanent
[no photo]	Oil	Low Fluid	Report	Unacceptable
	Left Front Fender	Chipped	Report	3

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Seat	Stained	Report	Permanent
	Left Rear Door	Multiple Scratches Light	Report	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.