



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
TRANSIT-150**
3 Door
Bodystyle/Series: **Vehicle XL
WAGON 130
WB**
Color: **WHITE**
Mileage: **70,071
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **1FMZK1ZM5JKB35988**
Work Order/
Stock Number: **000354619**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G422033V**
Vehicle Grade : **Grade 4.0**
Remarks: **-**
Announcements: **-**
Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

3rd Row Seat	ABS Brakes	Air Conditioning
Auxiliary Pwr Outlet	Bluetooth Connection	Brake Assist System
CD Player	Car Tire Size - LR tire size LT235/65SR16	Car Tire Size - RR tire size LT235/65SR16
Car Tire Size - RF tire size LT235/65SR16	Car Tire Size - LF tire size LT235/65SR16	Cruise Control
Cylinders - 6	Daytime Running Lights	Driver Air Bag
Empty Weight - 5488 lb	Floor Mats	Independent Climate Control
Intermittent Wipers	Keyless Entry	LF Tires - 8/32 inch
LR Tires - 7/32 inch	Leather Steering Wheel	MP3 Radio
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass. Air Bag
Power Brakes	Power Lock	Power Mirrors
Power Steering	Power Windows	Privacy Glass
RF Tires - 9/32 inch	RR Tires - 8/32 inch	Rear AC
Rear Defrost	Rear Parking Aid	Rear View Mirror
Reverse Camera	Seat Trim - Vinyl	Side Airbags - Front
Steering Wheel Audio Control	Telematics	Tilt Steering Wheel
Tire Brand - Front Left - LF tire mfg Toyo	Tire Brand - Front Right - RF tire mfg Toyo	Tire Brand - Rear Left - LR tire mfg Toyo
Tire Brand - Rear Right - RR tire mfg Generic	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Trip Computer	Two-Wheel Drive
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown




Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper/Cover	Multiple Scratches Heavy	Report	10 Or More
	Right Front Door	Chipped	Report	5
	Right Front Fender	Multiple Scratches Light	Report	6
[no photo]	Battery	Inoperable	Report	Repair Required
[no photo]	Oil	Low Fluid	Report	Unacceptable
	Left Front Fender	Multiple Scratches Light	Report	6
	Cab - Left	Multiple Dents/No Paint Damage	Report	6
	Front Bumper/Cover	Multiple Scratches Light	Report	6

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Chipped	Report	5
	Left Front Door	Multiple Scratches Light	Report	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.