



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
HYUNDAI
ELANTRA**

Bodystyle/Series: **4 Door Sedan
SE 4D
SEDAN AT**

Color: **WHITE**

Mileage: **19,567
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **5NPD74LF3LH610213**

Work Order/
Stock Number: **000354431**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G133643X**

Vehicle Grade : **Grade 4.5
APPROVED
BATTERY
\$79 LABOR
\$85 10/13
COMPELTED
10/14**

Remarks:

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes

Equipment

Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
ABS Brakes	Air Conditioning	Bluetooth Connection	
Brake Assist System	Car Tire Size - LR tire size P195/65TR15	Car Tire Size - RR tire size P195/65TR15	
Car Tire Size - RF tire size P195/65TR15	Car Tire Size - LF tire size P195/65TR15	Child Safety Locks	
Collision Avoidance	Cruise Control	Cylinders - 4	
Daytime Running Lights	Driver Air Bag	Dual Air Conditioning	
Empty Weight - 2844 lb	Floor Mats	Front Wheel Drive	
Front Wheel Drive	Independent Climate Control	Intermittent Wipers	
Keyless Entry	LF Tires - 7/32 inch	LR Tires - 7/32 inch	
Lane Departure System	MP3 Radio	Master Key - 1key(s)	
Motor Fuel Type - Gas	Pass-Through Rear Seat	Pass. Air Bag	
Power Brakes	Power Lock	Power Mirrors	
Power Steering	Power Windows	RF Tires - 8/32 inch	
RR Tires - 7/32 inch	Rear Defrost	Remote Trunk Release	
Reverse Camera	Seat Trim - Cloth	Security System	
Side Airbags - Front	Spare Tire	Steering Wheel Audio Control	
Stereo - AM/FM Radio	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Nexen	
Tire Brand - Front Right - RF tire mfg Nexen	Tire Brand - Rear Left - LR tire mfg Nexen	Tire Brand - Rear Right - RR tire mfg Nexen	
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission	
Trip Computer	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium		


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown



Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Battery	Inoperable	Report	Repair Required
	Right Rear Door	Multiple Scratches Light	Report	5
	Left Rear Door	Multiple Scratches Light	Report	6
	Left Front Wheel Cover	Bent	Replace	Replacement Required
	Left Front Door	Multiple Scratches Light	Report	5
	Left Qtr Panel	Multiple Scratches Light	Report	6
	Hood	Chipped	Report	5

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Multiple Scratches Light	Report	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.