



Approved
CR

Akron Auto Auction
2471 Ley Drive
Akron, OH 44319
3304365819/(330) 773-3921
lbeth@akronautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018
HYUNDAI
IONIQ
HYBRID
4 Door Sedan**

Bodystyle/Series: **BLUE 4D
HATCHBACK**

Color: **SILVER**

Mileage: **71,385
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **KMHC65LC1JU075584**

Work Order/
Stock Number: **000931117**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G130983V**

Vehicle Grade : **Grade 3.9**

AutoGrade : **3.9 - Average**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

ABS Brakes	Air Conditioning	Automatic Headlights
Bluetooth Connection	Brake Assist System	Car Tire Size - RR tire size P195/65HR15
Car Tire Size - RF tire size P195/65HR15	Car Tire Size - LR tire size P195/65HR15	Car Tire Size - LF tire size P195/65HR15
Child Safety Locks	Cruise Control	Cylinders - 4
Daytime Running Lights	Driver Air Bag	Dual Air Conditioning
Empty Weight - 2996 lb	Engine Immobilizer	Floor Mats
Front Wheel Drive	Front Wheel Drive	HD Radio
Independent Climate Control	Intermittent Wipers	Keyless Entry
Keyless Start	LF Tires - 7/32 inch	LR Tires - 8/32 inch
MP3 Radio	Master Key - 1key(s)	Motor Fuel Type - Other
Pass-Through Rear Seat	Pass. Air Bag	Power Brakes
Power Lock	Power Mirrors	Power Steering
Power Windows	RF Tires - 7/32 inch	RR Tires - 8/32 inch
Rear Defrost	Rear Spoiler	Reverse Camera
Seat Trim - Cloth	Security System	Side Airbags - Front
Steering Wheel Audio Control	Stereo - AM/FM Radio	Tilt Steering Wheel
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission
Trip Computer	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	XM Radio	



Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown

Chargeable Damages

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Wheel Cover	Chipped	Repair	3
	Left Rear Door	Chipped	Touch Up	2
	Left Rear Wheel Cover	Chipped	Repair	4
	Right Qtr Panel	Repainted	Report	Acceptable
	Right Rocker Panel Molding	Chipped	Touch Up	2
	Rear Bumper	Multiple Scratches Light	Report	4
	Right Front Door	Dent(S) W/No Paint Dmg	PDR	1/8 To 1/2 Inch
	Right Front Door	Multiple Scratches Heavy	Touch Up	3
	Hood	Chipped	Touch Up	2
	Left Qtr Panel	Multiple Scratches Heavy	Touch Up	2
	Left Rocker Panel Molding	Chipped	Touch Up	2
	Left Front Door	Chipped	Touch Up	2

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel Cover	Curb Rash	Repair	4 To 5 Inches
	Rf Mirror Cover	Chipped	Touch Up	3
	Right Rear Door	Dent(S) W/No Paint Dmg	PDR	1/8 To 1/2 Inch
	Right Rear Door	Scuffed	Report	1/8 To 1/2 Inch
	Right Rear Wheel Cover	Cracked	Replace	Replacement Required
	Windshield	Cracked	Replace	1/2 To 1 Inch
	Left Front Fender	Chipped	Touch Up	2
	Front Bumper	Chipped	Repair	6
	Left Front Door	Repainted	Report	Acceptable
	Left Front Fender	Repainted	Report	Acceptable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.