



Approved CR

IAA Metro DC
14149 Brandywine Rd
Brandywine, MD 20613
(301) 372-8876/(301) 372-8285
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
POLICE
INTERCEPTOR**

Bodystyle/Series: **Sport Utility
Vehicle -**

Color: **White**

Mileage: **72,068
(Verified)**

Turn-in Mileage: **-**

VIN: **1FM5K8AB5LGC70363**

Work Order/
Stock Number: **46388179**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G626324X**

Vehicle Grade : **Grade 2.3**

Remarks: **-**

Announcements:

- rear seats removed
- Warning light on check IAA OBD11 REPORT FOR DETAILS
- prior police

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes

Equipment


Seats:	Bench	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes
Additional Equipment:			
Car Tire Size - RF 255 / 60 R 18	Car Tire Size - LR 255 / 60 R 18	Car Tire Size - RR 255 / 60 R 18	
Car Tire Size - LF 255 / 60 R 18	LF Tires - 7/32 inch	LR Tires - 7/32 inch	
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - GOODYEAR	
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR	
Tire Model - LR - Eagle Enforcer	Tire Model - LF - Eagle Enforcer	Tire Model - RR - Eagle Enforcer	
Tire Model - RF - Eagle Enforcer			

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Drip Rail	Previous Repair	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Brakes	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Fender	Chipped	-	5
	Left Rear Wheel Cover	Broken	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Wheel Cover	Broken	-	Replacement Required
	Roof	Chipped	-	2
	Right Rear Seat	Missing	-	Replacement Required
	Left Rear Seat	Missing	-	Replacement Required
	Center Console	Missing	-	Replacement Required
	Trunk/Cargo Mat	Missing	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Door	Chipped	-	3
	Left Rear Door	Chipped	-	4
	Left Front Fender	Chipped	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.