Approved
CR

IAA High Desert
11385 G Avenue
Branch No 133
Hesperia, CA 92345
(760)949-8404/(760)949-0400
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 RAM 1500**
Bodystyle/Series:	**Crew Cab TRADESMAN**
Color:	**White**
Mileage:	**51,596 (Verified)**
Turn-in Mileage:	-
VIN:	**1C6RR7KG0GS396078**
Work Order/ Stock Number:	**46425878**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G623793S**
Vehicle Grade :	**Grade 3.0**
Remarks:	-
Announcements:	• REAR DOORS / WINDOWS INOPERABLE MAY BE INOPERABLE • SALVAGE STAMPED CERTIFICATE TO OBTAIN TITLE WILL BE ISSUED • CONDITION UNKNOWN • FORMER POLICE VEHICLE
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**No**

Equipment

Engine Size:	**3.6 L**	Pwr Steering:	**No**
Roof:	-	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	- /-	Rear Defroster:	**No**
Airbag:	-	Tilt Steering:	**No**
Seats:	-	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	-

Additional Equipment:

Car Tire Size - RR 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17	Car Tire Size - LF 265 / 70 R 17
Car Tire Size - LR 265 / 70 R 17	LF Tires - 7/32 inch	LR Tires - 6/32 inch
RF Tires - 7/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Wrangler SR-A	Tire Model - LR - w	Tire Model - RF - w
Tire Model - RR - w		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Warning - Traction Control	On	-	Unacceptable
	Warning - Tire Pressure	On	-	Unacceptable
	Aftermarket Accessory	Aftermarket	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	-	Repair Required
	Left Head Lamp	Faded	-	Acceptable
	Left Bed Side	Peeling	-	3 To 4 Inches
	Tailgate	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Right Bed Side	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Left Front Seat	Torn	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.