



Approved CR

IAA Colorado Springs
8500 Import Ct
Branch No 377
Colorado Springs, CO 80925
(719) 755-0862/(719) 715-0988
mgr-coloradosprings@iaai.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
F-250**
Bodystyle/Series: **Extended Cab
XL**
Color: **Dark Blue**
Mileage: **57,938
(Verified)**
Turn-in Mileage: **-**
VIN: **1FT7X2B62GEC75924**
Work Order/
Stock Number: **46305375**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G63-1398S**
Vehicle Grade : **Grade 3.1**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

LF Tires - 9/32 inch

LR Tires - 9/32 inch

RF Tires - 9/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - BFGOODRICH

Tire Brand - Front Right - BFGOODRICH

Tire Brand - Rear Left - BFGOODRICH

Tire Brand - Rear Right - BFGOODRICH

Tire Model - LF - All-Terrain T/A KO2

Tire Model - LR - All-Terrain T/A KO2

Tire Model - RF - All-Terrain T/A KO2

Tire Model - RR - All-Terrain T/A KO2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate Molding	Gouged	-	< 1/8 Inch
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Right Head Lamp	Faded	-	Repair Required
	Left Head Lamp	Faded	-	Repair Required
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	4 To 5 Inches
	Rear Bumper Step Pad	Bent	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Multiple Dents/Paint Damage	-	2
	Left Front Seat Cushion	Torn	-	1 To 2 Inches
	Left Front Seat Back	Torn	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.