Approved CR

IAA San Antonio-South
11275 South Zarzamora
Branch No 442
San Antonio, TX 78224
(210) 628-6770/(210) 628-6778
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 HYUNDAI ELANTRA**
Bodystyle/Series:	**4 Door Sedan SEL**
Color:	**Silver**
Mileage:	**30,335 (Verified)**
Turn-in Mileage:	-
VIN:	**5NPD84LF0JH390832**
Work Order/ Stock Number:	**46459196**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G13A0065**
Vehicle Grade :	**Grade 4.0**
Remarks:	-
Announcements:	• windshield cracked; Hail Damage
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment


Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 205 / 55 R 16	Car Tire Size - RF 205 / 55 R 16	Car Tire Size - LF 205 / 55 R 16
Car Tire Size - LR 205 / 55 R 16	LF Tires - 5/32 inch	LR Tires - 6/32 inch
RF Tires - 6/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - NEXEN
Tire Brand - Front Right - NEXEN	Tire Brand - Rear Left - NEXEN	Tire Brand - Rear Right - NEXEN
Tire Model - RR - Npriz AH8	Tire Model - RF - Npriz AH8	Tire Model - LR - Npriz AH8
Tire Model - LF - Npriz AH8		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Front Door Handle	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door Applique	Peeling	-	3 To 4 Inches
	Hood	Chipped	-	3
	Front Bumper	Multiple Scratches Heavy	-	3
	Rear Bumper	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Door Handle (Interior)	Worn	-	Replacement Required
	Left Rear Door	Light Scratch	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.