Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2018 RAM 1500**
Bodystyle/Series:	**Crew Cab TRADESMAN 4X4 5`7 BOX**
Color:	**White**
Mileage:	**53,514 (Verified)**
Turn-in Mileage:	-
VIN:	**1C6RR7KGXJS315868**
Work Order/ Stock Number:	**46367306**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G624125V**
Vehicle Grade :	**Grade 2.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment


Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Vinyl Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Memory**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Hydraulic Brakes**

Equipment


Additional Equipment:

Car Tire Size - RR 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17	Car Tire Size - LF 265 / 70 R 17
Car Tire Size - LR 265 / 70 R 17	LF Tires - 10/32 inch	LR Tires - 9/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - LF - Destination X/T	Tire Model - LR - Destination X/T	Tire Model - RF - Destination X/T
Tire Model - RR - Destination X/T		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Bent	-	6 To 7 Inches
	Grille	Chipped	-	5
	Right Front Door	Multiple Scratches Heavy	-	3
	Right Rocker Panel	Multiple Scratches Heavy	-	3
	Right Front Wheel	Corrosion	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Multiple Scratches Heavy	-	5
	Right Rear Wheel	Corrosion	-	1 To 2 Inches
	Rear Metal Bumper Painted	Multiple Dents/Paint Damage	-	2
	Tailgate	Multiple Scratches Heavy	-	2
	Tailgate Protective Cap	Missing	-	Replacement Required
	Left Rear Wheel	Corrosion	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door	Chipped	-	2
	Left Front Door	Chipped	-	2
	Left Front Wheel	Corrosion	-	1/2 To 1 Inch
	Roof	Chipped	-	1
	Left Bed Side	Multiple Dents/Paint Damage	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.