Approved
CR

Orlando Auto Auction
4636 W. Colonial Dr
Orlando, FL 32808
(407) 299-3904/(407) 294-6982
david.orlandoautoauction@gmail.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 FORD TRANSIT-350**
Bodystyle/Series:	**3 Door Wagon XL**
Color:	**WHITE**
Mileage:	**29,882 (Digital)**
Turn-in Mileage:	-
VIN:	**1FBZX2ZM6JKB42979**
Work Order/ Stock Number:	**0309017**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G434441V**
Vehicle Grade :	**Grade 2.9**
Remarks:	-
Announcements:	• DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE • ITEM DESCRIPTION; HOWEVER, THE ABSENCE OF ANY • INDICATED DEFICIENCIES DOES NOT MEAN THERE ARE • NONE.
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**

Equipment

Engine Size:	**3.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**CD Only**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**Rear Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Additional Equipment:

3rd Row Seat	Auxiliary Audio Input	Auxiliary Pwr Outlet
Backup camera and monitor	Bluetooth Connection	Brake Assist System
Car LF Tires - 6/32 inch	Car LR Tires - 7/32 inch	Car RF Tires - 10/32 inch
Car RR Tires - 9/32 inch	Car Tire Size - LF: LT235/65SR16 LR: LT235/65SR16 RF: LT235/65SR16 RR: LT235/65SR16	Cylinders - 6
Daytime Running Lights	Driver Adjustable Lumbar	Driver Illuminated Vanity Mirr
Driver Vanity Mirror	Electronic Stability Control	Floor Mats
Front Head Air Bag	Ignition Key - 1key(s)	Independent Climate Control
Intermittent Wipers	Keyless Entry - Left	LF Tires - 6/32 inch
LR Tires - 7/32 inch	Leather Steering Wheel	MP3 Radio
Misc. Special Features - Passenger Third Door, Airbag Disconnect Switch	Pass. Air Bag	Passenger Air Bag Sensor
Passenger Illuminated Vanity M	Passenger Vanity Mirror	Power Mirrors
Privacy Glass	RF Tires - 10/32 inch	RR Tires - 9/32 inch
Rear AC	Rear Bench Seat	Rear Head Air Bag
Side Airbags - Front	Smart Device Integration	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - OTHER
Tire Brand - Front Right - OTHER	Tire Brand - Rear Left - OTHER	Tire Brand - Rear Right - OTHER
Tire LF - 6/32 inch	Tire Pressure Monitor System	Tire RF - 10/32 inch
Tire Size - LF: LT235/65SR16 LR: LT235/65SR16 RF: LT235/65SR16 RR: LT235/65SR16	Tire Size - LF: LT235/65SR16 LR: LT235/65SR16 RF: LT235/65SR16 RR: LT235/65SR16	Transmission - Automatic Transmission w/ Overdrive
Trip Computer	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	WiFi Hotspot

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Seat Center Rear	Missing	Replace	Replacement Required
	Left Rear Seat	Missing	Replace	Replacement Required
	Right Rear Seat	Missing	Replace	Replacement Required
	Windshield	Cracked	Replace	> 12 Inches
	Left Front Door	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Left Fuel Door	Broken	Replace	Replacement Required
	Center Brake Light	Broken	Replace	Replacement Required
	Rear Bumper/Cover	Broken	Replace	Replacement Required
	Right Rear Cargo Door	Multiple Dents/Paint Damage	Repair	3
	Right Rear Door	Multiple Dents/No Paint Damage	Repair	10 Or More
	Right Qtr Panel	Torn	Replace	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Heavy Scratch	Refinish	2 To 3 Inches
	Left Front Seat Cushion	Torn	Repair	3 To 4 Inches
	Shifter Knob	Worn	Replace	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.