Approved
CR

Carriage Trade Auto Auction
1200 Ridge Pike
Conshohocken, PA 19428
215-CAR-SALE/(610) 834-8274
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 FORD F-250**
Bodystyle/Series:	**Extended Cab XL**
Color:	**WHITE**
Mileage:	**64,865 (Digital)**
Turn-in Mileage:	-
VIN:	**1FD7X2B68HED88001**
Work Order/ Stock Number:	**0181467**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G632857U**
Vehicle Grade :	**Grade 2.8**
Remarks:	-
Announcements:	• BODY/PAINT/RUST DAMAGE
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**No**
Engine Size:	**6.2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**CD Only**	Pwr Windows	**No**
Interior - Type/Color:	**- /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

4th Passenger Door	Automatic Headlights	Auxiliary Audio Input
Auxiliary Pwr Outlet	Backup camera and monitor	Bench Seating
Bluetooth Connection	Brake Assist System	Car LF Tires - 12/32 inch
Car LR Tires - 6/32 inch	Car RF Tires - 11/32 inch	Car RR Tires - 8/32 inch
Car Tire Size - LF: LT245/75R17 LR: LT245/75R17 RF: LT245/75R17 RR: LT245/75R17 SP: FULL SIZE	Cylinders - 8	Daytime Running Lights
Driver Adjustable Lumbar	Driver Restriction Features	Electrochromic Rearview Mirror
Electronic Stability Control	Engine Immobilizer	Front Head Air Bag
Front Tow Hooks	Ignition Key - 1key(s)	Intermittent Wipers
LF Tires - 12/32 inch	LR Tires - 6/32 inch	Limited Slip Differential
MP3 Radio	Misc. Special Features - Passenger Third Door, Airbag Disconnect Switch	Pass. Air Bag
Passenger Vanity Mirror	Privacy Glass	RF Tires - 11/32 inch
RR Tires - 8/32 inch	Rear Bench Seat	Rear Head Air Bag
Running Board	Side Airbags - Front	Smart Device Integration
Spare Tire - Full Size	Spare Tire Tread - 8/32 inch	Spare Wheel - Steel
Steering Wheel Audio Control	Telematics	Tilt Steering Wheel
Tire LF - 12/32 inch	Tire Pressure Monitor System	Tire RF - 11/32 inch
Tire Size - LF: LT245/75R17 LR: LT245/75R17 RF: LT245/75R17 RR: LT245/75R17 SP: FULL SIZE	Tire Size - LF: LT245/75R17 LR: LT245/75R17 RF: LT245/75R17 RR: LT245/75R17 SP: FULL SIZE	Tow Hitch
Transmission - Automatic Transmission w/ Overdrive	Transmission - Automatic Transmission	Trip Computer
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 8	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 7	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Left Front Door Edge	Chipped	Estimate Only	7
[no photo]	Left Running Board	Loose	Estimate Only	Repair Required
	Left Bed Side	Rust	Estimate Only	> 12 Inches
	Front Bumper	Dent(S) W/ Paint Dmg	Estimate Only	> 12 Inches
	Cab - Left	Dent(S) W/ Paint Dmg	Estimate Only	3 To 4 Inches
[no photo]	Left Rear Door	Multiple Scratches Light	-	2
	Rear Bumper	Dent(S) W/ Paint Dmg	Estimate Only	> 12 Inches
	Pickup Bed	Multiple Dents/Paint Damage	Estimate Only	6
	Right Bed Side	Rust	Estimate Only	4 To 5 Inches
[no photo]	Right Front Door Edge	Chipped	Estimate Only	5
	Roof	Hole(S)	Estimate Only	2 To 3 Inches
	Digital Display	Photo Only	Remove	None
	Vinyl Floor	Hole(S)	Estimate Only	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper Extension	Cracked	Estimate Only	4 To 5 Inches
[no photo]	Hood	Chipped	Estimate Only	5
	Steering Wheel	Worn	Estimate Only	Replacement Required
	Warning - Tire Pressure	On	Mechanical Check	Unacceptable
	Right Front Seat	Stained	Detail	Permanent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.