



Approved
CR

IAA Reno
4086 Peru Drive
Branch No 154
McCarran, NV 89434
(775) 636-8829/(775) 636-7280
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021 SUBARU
OUTBACK**
Bodystyle/Series: **Sport Utility
Vehicle
PREMIUM**
Color: **Silver**
Mileage: **122,789
(Verified)**
Turn-in Mileage: **-**
VIN: **4S4BTACCXM3218409**
Work Order/
Stock Number: **46312055**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G61-0795Y**
Vehicle Grade : **Grade 4.0**
Remarks: **-**
Announcements:

- SEE IAA
CONDITION
REPORT FOR
MORE
INFORMATION.

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather/Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 65 R 17	Car Tire Size - RF 225 / 65 R 17	Car Tire Size - LF 225 / 65 R 17
Car Tire Size - LR 225 / 65 R 17	LF Tires - 3/32 inch	LR Tires - 6/32 inch
RF Tires - 3/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - SAILUN
Tire Brand - Front Right - SAILUN	Tire Brand - Rear Left - SAILUN	Tire Brand - Rear Right - SAILUN
Tire Model - LF - Terramax HLT	Tire Model - LR - Terramax HLT	Tire Model - RF - Terramax HLT
Tire Model - RR - Terramax HLT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
 Tire Information Driver Side Size: 225 / 45 R 17 Brand: Goodyear Tread Depth: 6/32" Model: TerraSpeed HLT Passenger Side Size: 225 / 45 R 17 Brand: Goodyear Tread Depth: 6/32" Model: TerraSpeed HLT Passenger Front Size: 225 / 45 R 17 Brand: Goodyear Tread Depth: 6/32" Model: TerraSpeed HLT	Left Front Tire	Worn	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Tire	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.