



Approved CR

IAA Reno
4086 Peru Drive
Branch No 154
McCarran, NV 89434
(775) 636-8829/(775) 636-7280
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 RAM
1500
CLASSIC**
-
Bodystyle/Series: **TRADESMAN
4X4 6`4 BOX**
Color: **Blue**
Mileage: **70,786
(Verified)**
Turn-in Mileage: -
VIN: **1C6RR7FG1LS137944**
Work Order/
Stock Number: **46311953**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G62-1234X**
Vehicle Grade : **Grade 3.2**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair -
Order: -



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather/Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 17

Car Tire Size - RF 265 / 70 R 17

Car Tire Size - LF 265 / 70 R 17

Car Tire Size - LR 265 / 70 R 17

LF Tires - 14/32 inch

LR Tires - 14/32 inch

RF Tires - 15/32 inch

RR Tires - 14/32 inch

Tire Brand - Front Left - HERCULES

Tire Brand - Front Right - HERCULES

Tire Brand - Rear Left - HERCULES

Tire Brand - Rear Right - HERCULES

Tire Model - LF - Terra Trac A/T

Tire Model - LR - Terra Trac A/T

Tire Model - RF - Terra Trac A/T

Tire Model - RR - Terra Trac A/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Left Front Wheel	Corrosion	-	1/2 To 1 Inch
	Left Rear Wheel	Corrosion	-	1 To 2 Inches
	Tailgate	Chipped	-	6
	Rear Metal Bumper Painted	Multiple Scratches Heavy	-	2
	Right Rear Wheel	Corrosion	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Bed Side	Multiple Scratches Light	-	5
	Right Front Wheel	Corrosion	-	1/2 To 1 Inch
	Right Front Door	Multiple Scratches Light	-	2
	Hood	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.