



Approved CR

IAA Colorado Springs  
8500 Import Ct  
Branch No 377  
Colorado Springs, CO 80925  
(719) 755-0862/(719) 715-0988  
mgr-coloradosprings@iaai.com  
WHOLESALE ASSESSMENT ONLY

2018  
Make/Model: **CHEVROLET  
SILVERADO  
2500HD**  
Bodystyle/Series: **Crew Cab  
WT**  
Color: **Gray**  
Mileage: **70,864  
(Verified)**  
Turn-in Mileage: -  
VIN: **1GC1KUEG9JF224894**  
Work Order/  
Stock Number: **46371773**  
Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**  
Client Stock #: **G630653V**  
Vehicle Grade : **Grade 3.4**  
Remarks: -  
Announcements: -  
Certification : -  
Req. Prev. Repair -  
Order:



Drivable: Yes

### Equipment

|                        |                               |                 |                      |
|------------------------|-------------------------------|-----------------|----------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>No</b>            |
| Engine:                | <b>8-Cylinder Flex Fuel</b>   | Cruise Control: | <b>Yes</b>           |
| Engine Size:           | <b>6 L</b>                    | Pwr Steering:   | <b>Yes</b>           |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>           |
| Radio:                 | -                             | Pwr Windows     | <b>Yes</b>           |
| Interior - Type/Color: | <b>Vinyl Interior /GRAY</b>   | Rear Defroster: | <b>No</b>            |
| Airbag:                | <b>Driver Side Air Bag</b>    | Tilt Steering:  | <b>Yes</b>           |
| Seats:                 | <b>Bench</b>                  | Drive Type:     | <b>4-Wheel Drive</b> |
| Seat Count:            | -                             | Brakes:         | <b>Disc</b>          |

## Equipment

### Additional Equipment:

|                                        |                                     |                                       |
|----------------------------------------|-------------------------------------|---------------------------------------|
| Car Tire Size - LF 245 / 75 R 17       | Car Tire Size - LR 245 / 75 R 17    | Car Tire Size - RR 245 / 75 R 17      |
| Car Tire Size - RF 245 / 75 R 17       | LF Tires - 13/32 inch               | LR Tires - 6/32 inch                  |
| RF Tires - 14/32 inch                  | RR Tires - 6/32 inch                | Tire Brand - Front Left - BRIDGESTONE |
| Tire Brand - Front Right - BRIDGESTONE | Tire Brand - Rear Left - KELLY      | Tire Brand - Rear Right - KELLY       |
| Tire Model - RR - Edge A/T             | Tire Model - RF - dueler a/t ascent | Tire Model - LR - Edge A/T            |
| Tire Model - LF - dueler a/t ascent    |                                     |                                       |

## Non Chargeable Damages

| Photo                                                                               | Item               | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|--------------------|------------|--------|----------|
|    | Front Cover Center | Photo Only | -      | -        |
|    | Right Side Panel   | Photo Only | -      | -        |
|   | Left Side Panel    | Photo Only | -      | -        |
|  | Instrument Panel   | Photo Only | -      | -        |
|  | Rear Bumper        | Photo Only | -      | -        |
|  | Extra Photo 2      | Photo Only | -      | -        |
|  | Extra Photo 3      | Photo Only | -      | -        |
|  | Right Front Fender | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Extra Photo 4           | Photo Only | -      | -        |
|    | Extra Photo 5           | Photo Only | -      | -        |
|    | Extra Photo 6           | Photo Only | -      | -        |
|    | Left Front Fender       | Photo Only | -      | -        |
|    | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|   | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Photo - Dash            | Photo Only | -      | -        |
|  | Extra Photo 1           | Photo Only | -      | -        |
|  | Odometer                | Photo Only | -      | -        |
|  | Rear Seats              | Photo Only | -      | -        |
|  | Photo - Vin/Id Sticker  | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                             | Item   | Damage     | Action | Severity |
|-----------------------------------------------------------------------------------|--------|------------|--------|----------|
|  | Engine | Photo Only | -      | -        |
|  | Keys   | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item              | Damage                      | Action | Severity        |
|-------------------------------------------------------------------------------------|-------------------|-----------------------------|--------|-----------------|
|    | Inside Bed        | Multiple Dents/Paint Damage | -      | 4               |
|   | Left Front Fender | Multiple Scratches Heavy    | -      | 4               |
|  | Windshield        | Multiple Chips              | -      | 2               |
|  | Right Front Wheel | Peeling                     | -      | 4 To 5 Inches   |
|  | Right Bed Side    | Heavy Scratch               | -      | 1/8 To 1/2 Inch |

### Chargeable Damages

| Photo                                                                             | Item                    | Damage        | Action | Severity        |
|-----------------------------------------------------------------------------------|-------------------------|---------------|--------|-----------------|
|  | Tailgate                | Heavy Scratch | -      | 1/8 To 1/2 Inch |
|  | Left Front Seat Cushion | Cut           | -      | 1/8 To 1/2 Inch |
|  | Left Bed Side           | Heavy Scratch | -      | > 12 Inches     |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.