Approved
CR

Orlando Auto Auction
4636 W. Colonial Dr
Orlando, FL 32808
(407) 299-3904/(407) 294-6982
david.orlandoautoauction@gmail.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 CHEVROLET COLORADO 2WD WORK TR**
Bodystyle/Series:	**Crew Cab -**
Color:	**WHITE**
Mileage:	**18,096 (Digital)**
Turn-in Mileage:	-
VIN:	**1GCGSBEA3J1266520**
Work Order/ Stock Number:	**0318695**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G412922V**
Vehicle Grade :	**Grade 4.0**
Remarks:	-
Announcements:	• DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE • ITEM DESCRIPTION; HOWEVER, THE ABSENCE OF ANY • INDICATED DEFICIENCIES DOES NOT MEAN THERE ARE • NONE.
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**

Equipment

Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.5 L**	Pwr Steering:	**No**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**Rear Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Additional Equipment:

Automatic Headlights	Auxiliary Audio Input	Backup camera and monitor
Bluetooth Connection	Car LF Tires - 7/32 inch	Car LR Tires - 7/32 inch
Car RF Tires - 7/32 inch	Car RR Tires - 8/32 inch	Car Tire Size - LF: 265/70R16 LR: 265/70R16 RF: 265/70R16 RR: 265/70R16 SP: SPACE SAVER
Cylinders - 4	Daytime Running Lights	Driver Restriction Features
Electronic Stability Control	Engine Immobilizer	Front Head Air Bag
Ignition Key - 2key(s)	Keyless Entry - Left	LF Tires - 7/32 inch
LR Tires - 7/32 inch	MP3 Radio	Pass. Air Bag
Passenger Air Bag Sensor	Passenger Vanity Mirror	Power Driver Seat
RF Tires - 7/32 inch	RR Tires - 8/32 inch	Rear Bench Seat
Rear Head Air Bag	Security System	Side Airbags - Front
Smart Device Integration	Spare Tire - Space Saver	Spare Wheel - Aluminium
Tilt Steering Wheel	Tire Brand - Front Left - OTHER	Tire Brand - Front Right - OTHER
Tire Brand - Rear Left - OTHER	Tire Brand - Rear Right - OTHER	Tire LF - 7/32 inch
Tire Pressure Monitor System	Tire RF - 7/32 inch	Tire Size - LF: 265/70R16 LR: 265/70R16 RF: 265/70R16 RR: 265/70R16 SP: SPACE SAVER
Tire Size - LF: 265/70R16 LR: 265/70R16 RF: 265/70R16 RR: 265/70R16 SP: SPACE SAVER	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	

Non Chargeable Damages

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 8	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 9	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Multiple Scratches Heavy	Touch Up	2
	Left Head Lamp	Faded	Repair	Repair Required
	Right Head Lamp	Faded	Repair	Repair Required
	Left Front Wheel	Rust	Refinish	Repair Required
	Left Rear Wheel	Rust	Refinish	Repair Required
	Right Rear Wheel	Rust	Refinish	Repair Required
	Right Front Wheel	Rust	Refinish	Repair Required
	Frame	Rust	Refinish	Naaa Acceptable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.