



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
F-250**
Bodystyle/Series: **2 Door
Vehicle XL
REG CAB**
Color: **WHITE**
Mileage: **14,349
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **1FDBF2A60HEE07218**
Work Order/
Stock Number: **000355131**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G432668U**
Vehicle Grade : **Grade 2.4**
Remarks: **-**
Announcements: **-**
Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	No
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	No
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

ABS Brakes	Automatic Headlights	Auxiliary Pwr Outlet
Bench Seating	Bluetooth Connection	Brake Assist System
CD Player	Car Tire Size - LF tire size LT245/75SR17	Car Tire Size - LR tire size LT245/75SR17
Car Tire Size - RF tire size LT245/75SR17	Car Tire Size - RR tire size LT245/75SR17	Cylinders - 8
Daytime Running Lights	Driver Air Bag	Empty Weight - 5683 lb
Engine Immobilizer	Intermittent Wipers	LF Tires - 13/32 inch
LR Tires - 3/32 inch	MP3 Radio	Master Key - 1key(s)
Motor Fuel Type - Gas	Pass. Air Bag	Power Brakes
Power Lock	Power Steering	Privacy Glass
RF Tires - 13/32 inch	RR Tires - 3/32 inch	Rear View Mirror
Seat Trim - Vinyl	Side Airbags - Front	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Firestone
Tire Brand - Front Right - RF tire mfg Firestone	Tire Brand - Rear Left - LR tire mfg Firestone	Tire Brand - Rear Right - RR tire mfg Firestone
Tire Pressure Monitor System	Tow Hitch	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Trip Computer	Two-Wheel Drive
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown


Non Chargeable Damages



Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Multiple Scratches Light	Report	10 Or More
	Inside Bed	Multiple Dents/Paint Damage	Report	10 Or More
	Left Bed Side	Peeling	Report	> 12 Inches
	Cab - Left	Peeling	Report	11 To 12 Inches
	Left Head Lamp	Faded	Report	Acceptable
	Lift Gate	Multiple Scratches Heavy	Report	10 Or More
	Left Front Door	Multiple Scratches Light	Report	3
	Left Front Fender	Multiple Scratches Light	Report	2
	Left Front Seat	Worn	Report	Acceptable
	Right Cab Side	Peeling	Report	11 To 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	Report	Acceptable
	Rear Bumper	Multiple Dents/No Paint Damage	Report	2
	Rear View Mirror	Aftermarket	Report	Acceptable
	Roof	Chipped	Report	3
	Right Front Door	Multiple Scratches Light	Report	3
	Right Front Fender	Multiple Scratches Light	Report	3
[no photo]	Left Rear Tire	Worn	Replace	Replacement Required
	Center Console	Worn	Report	Acceptable
[no photo]	Right Rear Tire	Worn	Replace	Replacement Required
[no photo]	Right Bed Side	Multiple Scratches Heavy	Report	6
[no photo]	Oil	Low Fluid	Report	Unacceptable
	Hood	Chipped	Report	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.