



Approved CR

IAA Knoxville  
3634 E. Governor John Sevier Hwy  
Branch No 754  
Knoxville, TN 37914  
(865) 525-7349/(865) 522-8813  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2024  
HYUNDAI  
TUCSON**

Bodystyle/Series: **Sport Utility  
Vehicle SE**

Color: **Silver**

Mileage: **1 (Unverified)**

Turn-in Mileage: **-**

VIN: **5NMJA3DE9RH392076**

Work Order/  
Stock Number: **46372240**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalessupport@gsa.gov**

Client Stock #: **G41B1229**

Vehicle Grade : **Grade 0.7**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: No

### Equipment

|                        |                               |                 |                          |
|------------------------|-------------------------------|-----------------|--------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>No</b>                |
| Engine:                | <b>4-Cylinder Gas</b>         | Cruise Control: | <b>Yes</b>               |
| Engine Size:           | <b>2.5 L</b>                  | Pwr Steering:   | <b>Yes</b>               |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>               |
| Radio:                 | <b>-</b>                      | Pwr Windows     | <b>Yes</b>               |
| Interior - Type/Color: | <b>Cloth Interior /BLACK</b>  | Rear Defroster: | <b>Yes</b>               |
| Airbag:                | <b>-</b>                      | Tilt Steering:  | <b>Yes</b>               |
| Seats:                 | <b>Bench</b>                  | Drive Type:     | <b>Front Wheel Drive</b> |
| Seat Count:            | <b>-</b>                      | Brakes:         | <b>Anti Lock Brakes</b>  |

## Equipment

### Additional Equipment:

Car Tire Size - LR 235 / 65 R 17

Car Tire Size - RR 235 / 65 R 17

Car Tire Size - RF 235 / 65 R 17

Car Tire Size - LF 235 / 65 R 17

LF Tires - 5/32 inch

LR Tires - 7/32 inch

RF Tires - 5/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - KUMHO

Tire Brand - Front Right - KUMHO

Tire Brand - Rear Left - KUMHO

Tire Brand - Rear Right - KUMHO

Tire Model - LF - Crugen HP71

Tire Model - LR - Crugen HP71

Tire Model - RF - Crugen HP71

Tire Model - RR - Crugen HP71

## Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|    | Photo - Vin/Id Sticker | Photo Only | -      | -        |
|    | Engine                 | Photo Only | -      | -        |
|   | Keys                   | Photo Only | -      | -        |
|  | Front Cover Center     | Photo Only | -      | -        |
|  | Right Side Panel       | Photo Only | -      | -        |
|  | Left Side Panel        | Photo Only | -      | -        |
|  | Instrument Panel       | Photo Only | -      | -        |
|  | Rear Bumper            | Photo Only | -      | -        |

| Non Chargeable Damages                                                              |                    |            |        |                      |
|-------------------------------------------------------------------------------------|--------------------|------------|--------|----------------------|
| Photo                                                                               | Item               | Damage     | Action | Severity             |
|    | Extra Photo 2      | Photo Only | -      | -                    |
|    | Extra Photo 3      | Photo Only | -      | -                    |
|    | Right Front Fender | Photo Only | -      | -                    |
|    | Extra Photo 4      | Photo Only | -      | -                    |
|    | Extra Photo 5      | Photo Only | -      | -                    |
|   | Extra Photo 6      | Photo Only | -      | -                    |
|  | Core Support       | Broken     | -      | Replacement Required |
|  | Right Front Rail   | Broken     | -      | Replacement Required |
|  | Extra Photo 7      | Photo Only | -      | -                    |

### Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Left Front Fender       | Photo Only | -      | -        |
|    | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|    | Right Rear Bumper/Cover | Photo Only | -      | -        |
|    | Photo - Dash            | Photo Only | -      | -        |
|    | Extra Photo 1           | Photo Only | -      | -        |
|   | Odometer                | Photo Only | -      | -        |
|  | Rear Seats              | Photo Only | -      | -        |


### Chargeable Damages

| Photo                                                                               | Item                    | Damage   | Action | Severity             |
|-------------------------------------------------------------------------------------|-------------------------|----------|--------|----------------------|
|  | Left Front Fender Liner | Missing  | -      | Replacement Required |
|  | Airbag - Front Left     | Deployed | -      | Replacement Required |

### Chargeable Damages

| Photo                                                                               | Item                       | Damage        | Action | Severity             |
|-------------------------------------------------------------------------------------|----------------------------|---------------|--------|----------------------|
|    | Lf Mirror Cover            | Light Scratch | -      | 2 To 3 Inches        |
|    | Front Bumper               | Missing       | -      | Replacement Required |
|    | Grille                     | Missing       | -      | Replacement Required |
|   | Right Head Lamp            | Broken        | -      | Replacement Required |
|  | Radiator                   | Broken        | -      | Replacement Required |
|  | Front Bumper Reinforcement | Broken        | -      | Replacement Required |

### Chargeable Damages

| Photo                                                                               | Item                     | Damage               | Action | Severity             |
|-------------------------------------------------------------------------------------|--------------------------|----------------------|--------|----------------------|
|    | Hood                     | Severe Damage        | -      | Replacement Required |
|    | R Daylight Running Light | Missing              | -      | Replacement Required |
|    | Right Front Fender       | Dent(S) W/ Paint Dmg | -      | 5 To 6 Inches        |
|   | Right Front Tire         | Flat                 | -      | Repair Required      |
|  | Right Front Fender Liner | Missing              | -      | Replacement Required |
|  | Right Front Door         | Chipped              | -      | 1                    |

### Chargeable Damages

| Photo                                                                             | Item               | Damage                 | Action | Severity             |
|-----------------------------------------------------------------------------------|--------------------|------------------------|--------|----------------------|
|  | Lift Gate          | Chipped                | -      | 2                    |
|  | Left Rear Door     | Dent(S) W/No Paint Dmg | -      | 1 To 2 Inches        |
|  | Lf Fender Cladding | Missing                | -      | Replacement Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.