



Approved CR

IAA Springfield
1155 N Eldon Ave, Building B
Branch No 531
Springfield, MO 65803
(417) 863-8976/(417) 865-5466
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 RAM
3500**
Bodystyle/Series: **Crew Cab
TRADESMAN
4X4 8' BOX**
Color: **White**
Mileage: **39,730
(Verified)**
Turn-in Mileage: **-**
VIN: **3C63R3GL2HG710519**
Work Order/
Stock Number: **46357386**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G630828U**
Vehicle Grade : **Grade 3.5**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment


Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment



Additional Equipment:

Car Tire Size - RR 275 / 70 R 18	Car Tire Size - RF 275 / 70 R 18	Car Tire Size - LF 275 / 70 R 18
Car Tire Size - LR 275 / 70 R 18	LF Tires - 9/32 inch	LR Tires - 12/32 inch
RF Tires - 9/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - NITTO
Tire Brand - Front Right - NITTO	Tire Brand - Rear Left - NITTO	Tire Brand - Rear Right - NITTO
Tire Model - LF - Dura Grappler Highway Terrain	Tire Model - LR - Dura Grappler Highway Terrain	Tire Model - RF - Dura Grappler Highway Terrain
Tire Model - RR - Dura Grappler Highway Terrain		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Left Bed Side	Heavy Scratch	-	1/8 To 1/2 Inch
	Inside Bed	Heavy Scratch	-	> 12 Inches
	Right Front Seat Cushion	Torn	-	1/2 To 1 Inch
	Roof	Dent(S) W/ Paint Dmg	-	4 To 5 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	R Cab Corner Panel	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.