



Approved CR

IAA Eugene
1000 Bethel Drive
Branch No 309
Eugene, OR 97402
(541) 689-4000/(541) 689-0083
WHOLESALE ASSESSMENT ONLY

2017
Make/Model: **CHEVROLET
SILVERADO
3500HD**
Bodystyle/Series: **Crew Cab
WT**
Color: **White**
Mileage: **116,958
(Verified)**
Turn-in Mileage: -
VIN: **1GC4KCY8HF218885**
Work Order/
Stock Number: **46361322**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G632405U**
Vehicle Grade : **Grade 2.7**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair -
Order: -



Drivable: Yes

Equipment


Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 275 / 70 R 18	Car Tire Size - LF 275 / 70 R 18	Car Tire Size - RF 275 / 70 R 18
Car Tire Size - LR 275 / 70 R 18	LF Tires - 8/32 inch	LR Tires - 5/32 inch
RF Tires - 9/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - MAZAMA
Tire Brand - Front Right - MAZAMA	Tire Brand - Rear Left - MAZAMA	Tire Brand - Rear Right - MAZAMA
Tire Model - RR - Open Range A/T Plus	Tire Model - RF - Open Range A/T Plus	Tire Model - LR - Open Range A/T Plus
Tire Model - LF - Open Range A/T Plus		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Tailgate	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Left Tail Light	Heavy Scratch	-	Replacement Required
	Left Bed Side	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailpipe/Exhaust Tip	Bent	-	Replacement Required
	Front Valance	Broken	-	Replacement Required
	Hood	Chipped	-	3
	Right Bed Side	Multiple Scratches Heavy	-	2
	Rear Metal Bumper Chrome	Multiple Dents/No Paint Damage	-	3
	Left Rear Door	Dent(S) W/ Paint Dmg	-	< 1/8 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Chipped	-	1
	Left Front Seat Cushion	Stained	-	Permanent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.