



Approved CR

Rawls Auto Auction Inc.
2818 Pond Branch Rd.
Leesville, SC 29070
(803) 859-5111/(803) 859-0517
wendyc@rawlsautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 RAM
2500**

Bodystyle/Series: **2 Door Pickup
Truck
TRADESMAN
REG CAB**

Color: **WHITE**

Mileage: **28,080
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **3C7WR4AJ2JG322606**

Work Order/
Stock Number: **000381195**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G433327V**

Vehicle Grade : **Grade 2.5**

Remarks: **-**

Announcements:

- HEMI /
SERVICE
UTILITY
- ABS & TRAC
CNTRL
LIGHTS ON

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.4 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	AM/FM Radio	Pwr Windows	No
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes


Equipment

Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
ABS Brakes	Air Conditioning	Automatic Headlights	
Bluetooth Connection	Brake Assist System	Car Jack	
Car Tire Size - LR tire size LT275/70SR18	Car Tire Size - LF tire size LT275/70SR18	Car Tire Size - RR tire size LT275/70SR18	
Car Tire Size - RF tire size LT275/70SR18	Cruise Control	Cylinders - 8	
Daytime Running Lights	Driver Air Bag	Electrochromic Rearview Mirror	
Empty Weight - 6012 lb	Engine Immobilizer	Hand Tool Kit	
Intermittent Wipers	LF Tires - 12/32 inch	LR Tires - 10/32 inch	
MP3 Radio	Master Key - 2key(s)	Motor Fuel Type - Gas	
OK Odor	Pass. Air Bag	Power Brakes	
Power Steering	RF Tires - 12/32 inch	RR Tires - 12/32 inch	
Rear View Mirror	Reverse Camera	Seat Trim - Vinyl	
Side Airbags - Front	Spare Tire	Stereo - AM/FM Radio	
Tilt Steering Wheel	Tilt Wheel	Tire Brand - Front Left - LF tire mfg Other	
Tire Brand - Front Right - RF tire mfg Other	Tire Brand - Rear Left - LR tire mfg Other	Tire Brand - Rear Right - RR tire mfg Other	
Tire Pressure Monitor System	Tow Hitch	Traction Control	
Transmission - Automatic Transmission	Two-Wheel Drive	Wheels Front Left - Steel	
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Extra Photo 8	Photo Only	Estimate Only	Unknown
	Extra Photo 9	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Bluetooth	Clear History	Remove	Removal Required
	Inside Bed	Multiple Scratches Heavy	Repair	10 Or More
	Left Bed Side	Multiple Scratches Heavy	Repair	10 Or More
	Left Front Door	Multiple Dents/Paint Damage	Repair	10 Or More
	Right Bed Side	Multiple Scratches Heavy	Repair	10 Or More
	Rear Bumper	Multiple Scratches Heavy	Repair	10 Or More
	Right Front Door	Multiple Dents/Paint Damage	Repair	10 Or More
	Tailgate	Multiple Scratches Heavy	Repair	10 Or More
	Warning - Traction Control	On	Report	Unacceptable
	Warning Light - Abs	On	Report	Unacceptable
[no photo]	Overall Vehicle	Multiple Scratches Light	Wet Sand	10 Or More
[no photo]	Front Bumper	Chipped	Touch Up	5
[no photo]	Hood	Multiple Dents/No Paint Damage	PDR	2
[no photo]	Left Front Fender	Dent(S) W/ Paint Dmg	Report	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
[no photo]	Right Front Fender	Dent(S) W/No Paint Dmg	PDR	1/2 To 1 Inch
[no photo]	Roof	Multiple Dents/No Paint Damage	PDR	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.