Approved
CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2013 BLUE BIRD SCHOOL BUS / TRANSIT BUS**
Bodystyle/Series:	- -
Color:	**White**
Mileage:	**34,396 (Verified)**
Turn-in Mileage:	-
VIN:	**1BABHCPA2DF295469**
Work Order/ Stock Number:	**45690498**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G320810W**
Vehicle Grade :	**Grade 2.0**
Remarks:	-
Announcements:	• REPAIRS OR REPLACEMENT MAY BE NEEDED, TOWED IN, MUST BE TOWED OUT • CONDITION UNKNOWN, PARTS MAY BE MISSING • SALVAGE STAMPED CERTIFICATE TO OBTAIN TITLE WILL BE ISSUED
Certification :	-
Req. Prev. Repair Order:	-

Drivable: No

Equipment

Transmission:	-	A/C:	**No**

Equipment

Engine:	**6-Cylinder Diesel**	Cruise Control:	**No**
Engine Size:	**6.7 L**	Pwr Steering:	**No**
Roof:	-	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	- /-	Rear Defroster:	**No**
Airbag:	-	Tilt Steering:	**No**
Seats:	-	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	-

Additional Equipment: -

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Abs	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning Light - Brakes	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Corner Panel	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Right Front Tire	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Tire	Worn	-	Replacement Required
	Left Rear Tire	Worn	-	Replacement Required
	Left Front Tire	Worn	-	Replacement Required
	Rear Metal Bumper Painted	Rust	-	> 12 Inches
	Front Metal Bumper Painted	Rust	-	2 To 3 Inches
	Roof	Enviro Paint Damage	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.